



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003286/Uqy3q2	
			Date: 24/04/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SDV 3268L	Veh. Inspected	GBD 9897A
	Policy No.	D22MTPV01010670	Coverage (\$)	0.00
	Claim No.	CMTD2301251/RUC	Excess (\$)	0.00
	Assign From	BETTY WONG	Assign Date	29/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	CITROEN BERLINGO (A)	c.c	1560
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	VF77F9HF8EJ847854	Colour	WHITE
	Odometer	253247 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	6 mm
	L/H Front Tyre	195/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	28/03/2023	Inspection Date	29/03/2023
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	