

CT 1

TOTAL

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/03/2023

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB159L
Case Reference Number	BUS/03/23/7023
Registration Date	10/20/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	CITARO O530
Name of Driver	Jiang Jijun
Type of Accident	Side Swipe
Accident Date and Time	3/27/2023 5:01 PM
Accident Reported Date and Time	3/28/2023 4:31 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB159L - Right view mirror dislodged (dangling) PC8679J (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	3/29/2023 12:37 PM
Chassis Number	WEB62808323122699
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$265.00	\$0.00 132.50
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$1,707.72	\$0.00
Total Other Cost	\$200.00	\$0.00
TOTAL COST	\$2,172.72	\$0.00
Lump Sum Total	\$2,150.00	\$0.00
Number of Repair Days	1.0	0.5
Prepared / Adjusted By	Kok Khoo Goh	
ARC / Surveyor Sign Off Date	29/03/2023 12:39 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Tan Jiah 97495744
WP 20/3/23 @ 10am -
4/5 Resurvey after repair
Tan Jiah C (Whentib-wr
0.5 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number : 63685592	
Estimator Telephone Number : 68662623	
Accident Reporting Number : 68662672	

Date Generated : 29/03/2023

User ID : JeongCH

Part 1 - Labour Works

Section D - Details of Repair Estimates

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$265.00	132.50
Total Labour	\$265.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Spray Painting & Panel Beating		

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	200 ✓ xxxxxx
Total Other Costs	\$200.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009873	ENGINE	0018106216	MIRROR,VIEW:FRONT RH,AUTO,MB CITARO O530	1.00	\$2,371.83	10.00	\$2,134.65	Replace	bro ✓
Total					\$2,371.83		\$2,134.65		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2134.65
20% - 1707.72
200
132.50
2040.22
1/s\$2050
0.5 days