

ASS. REF: 1001

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMB 264R Yr Regn: 2012, May

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MAN NL 320F C.C. 10518

Colour: Multi A/C: Insured / Std / NI / NA

Sp. Reading: 637648 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WM 1A 2227 22700 1306

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI S/Rim / STD A/Rim or

Tyre Size: F: 275/70K 22.5

R: 2 (O)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fallen

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. _____ D.O.I. 30/3/25

Survey held at SMRT WL

Des. of Damages Frt / Rear / O/S / N/S / WC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. \$ _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

Report Format: _____

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/03/2023

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB264R
Case Reference Number	BUS/03/23/7022
Registration Date	5/4/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Liu Bin
Type of Accident	Head to Rear
Accident Date and Time	3/28/2023 11:10 AM
Accident Reported Date and Time	3/28/2023 4:13 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB264R - Bus rear bumper and engine cover dented. Coolant leaking. SMP9589X (TP) - INSURED WITH AIG
Prepared Date and Time	3/29/2023 2:09 PM
Chassis Number	WMAA22ZZ2C7001306
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00 1060
Total Spray Cost	\$786.00	\$0.00 616
Total Spare Part Cost	\$4,490.20	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$6,866.20	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3 days
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	29/03/2023 2:29 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Taufik 97495749
- wp' 30/3/23 @ 10am
L/S Resurvey after repair
taufik@lkkauto.com
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/03/2023

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, If applicable
TO REMOVE & FIX FRT W/SCREEN	\$1,590.00	1060
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	616
Total Spray Painting & Panel Beating	\$786.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6014033			PIPE,WATER:COOLANT,MAN A22	1.00	\$476.80	10.00	\$429.12	Replace	bt✓
6010900			SLEEVE,REDUCING:FOR MAN A22 BUS	1.00	\$58.60	10.00	\$52.74	Replace	bt✓
6010876			SLEEVE,SINGLE FOLD:FOR MAN A22 BUS	1.00	\$155.60	10.00	\$140.04	Replace	bt✓
6011407	Body		DOOR,ENGINE:REAR,MAN A22 'C' SERIES	1.00	\$1,625.00	10.00	\$1,462.50	Replace	R✓
6010372	Body	4001F09-ACCE5021	PANEL,REFLECTOR:REAR,LH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	X
6010373	Body	4001F09-ACCE5020	PANEL,REFLECTOR:REAR,RH,FOR MAN BUS	1.00	\$107.00	10.00	\$96.30	Replace	X
6010463	Body	S01001-CW006	FRAME,REAR BUMPER:FOR MAN A22 BUS	1.00	\$1,423.20	10.00	\$1,280.88	Replace	bt✓
6010464	VM	S01001-CW002	BRACKET,ATTACHMENT:FOR MAN A22 BUS	1.00	\$569.30	10.00	\$512.37	Replace	bt✓
6011408	Body		BUMPER:REAR,CENTRE,MAN A22 'C' SERIES	1.00	\$1,625.00	10.00	\$1,462.50	Replace	cr✓
			60KM/H STICKER	1.00	\$5.00	0.00	\$5.00	Replace	nei✓
			SMRT STICKERS	1.00	\$75.00	0.00	\$75.00	Replace	nei✓
Total					\$6,227.50		\$5,612.75		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									