

DATE:

ASS. REC. BY: Alia kumal

REF: CS/AG123003354/Wvy3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 () TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: AGI
 Policy No. _____
 Claims No. C20021230
 Sum Insured: _____ Excess: -
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Sal. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03 days Res.: Yes or No
 Lump Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FBJ 8338 Y Yr Regn: 2514 12020
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: Adiva ADI 200 cc 133
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 19898.7 T/Radio: Insured / Std / NI / NA
 Eng/No: SR20A00000479
 C/No: RGVSR20FIKAD00075
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 130/60 R13
 R: 140/60 R13

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / FI / SUMI /
 TOYO / YOKO or _____

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. _____ mm
 D.O.A. 270312023 D.O.I. 30103123 1457
 Survey held at Mah Pte Ltd

Des. of Damages: Frt / Rear / OS / BS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair Range
	03 days
	\$1.5k - \$2k
	Balance: 92M
	Yearly: \$1.6k
	MV: \$12k
6/4/23	Submit CTL-mv:\$12k lta:\$5576 nv:6424
	LTA: \$5576
	NV: \$6424

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ - RS. \$ _____

Photos

Others

TOTAL

Note:

Damage not accident related, likely due to pre-mature material fatigue.

Veron Chen (LKKAUTO)

From: Natarajan Kavidha Rajan <kavidha.n@budgetdirect.com.sg>
Sent: Thursday, 30 March 2023 12:34 PM
To: admin-d; SUR; assignments
Subject: FW: Survey || FBJ8338Y || Claim: C20021230 , Claimed Policy: P20819554R00 , Policy Holder: Him Peng Yong
Attachments: C20021230 Him Peng Yong.zip

Dear Team,

Please assist to survey the above Motorcycle, FBJ8338Y.

ADD: Mah Pte Ltd 1179 Serangoon Rd, Singapore 328232
Contact person: Ms. Wani
Contact number: 64200428

PH has filed for OD based on damage due to bike going over road hump.

2 brackets from the chassis broke off and vehicle unable to repair.

Please provide us your insight if this damage is purely due to wear and tear.

Attached GIA report, password is the car plate number.

Thank you.

Best Regards,
Kavidha
Executive, Claims

T +65 6989 3693
F +65 6725 0853
E kavidha.n@budgetdirect.com.sg

It pays to choose

**Budget
Direct**
insurance



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Damage due to pre-mature
material
material for fatigue
and not accident
related.