

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR22011481/Svy3m4-	
		NIDUIGEDIAL DADIC			1	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	14/04/2023	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHB 1665U	Veh. Inspected		FBQ 9508E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/11/22/2019	Excess (\$)		0.00	
	Assign From	ANA	Assign Date		29/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA XMAX 300	c.c		292	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	MH3SH0847KK009313	Colour		BLACK	
	Odometer	45305 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	120/70-15	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-14	PIRELLI		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/11/2022	Inspection Date	е	16/11/2022	
	Survey held at	PRECISE AUTO SERVICE				
		NO.1 KAKI BUKIT AVE 6				
		#02-34/36 SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.					
5b.	S)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.  Estimate Days of Repair					
35.	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					
	LOTINI, CILD NOICE	WILL ENGLISH SICKELAIN.		- 1101KI	ng Days	