

(08/11/13)

ASS. REC. BY:

REF CS6/AIS 23003370/HVY3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$ 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$ 235,000

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKA 6778P Yr Regn: 27/6 / 2019Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MERCEDES BENZ c.c. 1991Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: ? T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2573502A024099Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or ?Brake: Inorder / Jammed / Leaked / Burnt or ?

Modl: Nil / S/Rlm / STD A/Rlm or _____

Tyre Size: F: ?R: ?

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ?

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 20/3/2023 D.O.I. 5/4/2023Survey held at DESKTOP SURVEYDes. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NET VALUE \$ 120,000

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

> Back to OneMotoring

D.O.A. : 20/3/2023
Bal. : 6yrs 3.2mths
M.V. : \$235,000

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	375F
Vehicle Details	
Vehicle No.:	SKA6778P
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Apr 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLS350 COUPE (R19 LED SR)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	26492030049537
Chassis No.:	WDD2573502A024099
Maximum Power Output:	230.0 kW (308 bhp)
Open Market Value:	\$83,756.00
Original Registration Date:	27 Jun 2019
First Registration Date:	27 Jun 2019
Transfer Count:	①
Actual ARF Paid:	\$122,761.00 / 650% =
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2029 //
PARF Rebate Amount:	\$92,070.00 61,380.
Intended COE Rebate Details	
COE Expiry Date:	26 Jun 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,906.00
COE Rebate Amount:	\$22,291.00
Total Rebate Amount:	\$114,361.00

The information contained herein is correct as at 05 Apr 2023

OK

Net Value = 120,639

31,320

30,250

28,790

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001851344-01	Date of Loss:	20/03/2023
Vehicle Reg. No.:	SKA6778P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Tai Chung Hao		
Make/Model:	MERCEDES-BENZ CLS350, 2.0 COUPE (R19 LED SR) (A)	Vehicle Reg. Date:	27/06/2019
Vehicle Colour:	Blue		
Engine No:	26492030049537	Chassis No:	WDD2573502A024099
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 2		
Present Location:	CITY AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	5,383.40
Miscellaneous Items	0.00
Labour	860.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	6,243.40
- Excess (S\$)	600.00
(S\$)	5,643.40
+ GST 8.00% (S\$)	451.47
Nett Amount (S\$)	6,094.87

This claim is handled by: VRONICA

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Mar 2023)

Parts: N/A MERCEDES-BENZ CLS350 2.0 COUPE (R19 LED SR) (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: City Auto Pte Ltd/SKA6778P/30/03/2023 13:35

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH headlamp	0.00	0.00	*3,520.00 F ?
2	1		*Front bumper	0.00	0.00	*1,350.00 F cut
3	1		*Front bumper retainer	0.00	0.00	*24.00 F NEC
Sub Total (\$)						4,894.00
+ Margin on L,N Items 10.00% (\$)						489.40
Total Parts (\$)						5,383.40

F=Franchise part.

City Auto Pte Ltd/SKA6778P/30/03/2023 13:35. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	- To check wiring and lighting	New	60.00 ?
2	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	300.00 200
3	- Spray painting on affected and replace parts	New	500.00 200
Gross Labour Cost (S\$)			860.00

City Auto Pte Ltd/SKA6778P/30/03/2023 13:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 2 DAYS

- NOT AUTHORISE
- EXCESS \$ 600
- P/P OR L/S REPAIR?
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts' prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: