

(08/11/13) wef

ASS. REC. BY: PM

REF:

CS/EG/23003379/RNG3

4380

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TR / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLM 6282Cat Workshop m/s LCRof 4, 3LN ROADInsured: EG1

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 66K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM 6282C Yr Regn: 2017 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SSANGYONG TUVOL XLV1.6G c.c 1597Colour: RED A/C: Insured / Std / NI / NASp. Reading: 107570 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPT36B.IVSHPI496646Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

RYOANZ

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 25/03/23D.O.I. 31/03/23

Survey held at

LCRDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 33K

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road Motorway Building Singapore 169205

Tel: 6468-2200 fax: 6278-5535

GST:20000606-K RCB NO: 20000606-K

M/S:ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec
Tower Three Singapore 038988
TEL: 6829 9925

ATTN: MOTOR CLAIM DEPARTMENT

Your Ref No:

Claim Type: Third Party

Accident Date: 25/03/2023

TP Veh Reg No: SLL8333G

LABOUR: \$400.00 SPRAY PAINT: \$450.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate No: WQT0000066

Date: 28 MAR 2023

Policy No:

Veh Reg No: SLM6282C

Make/Model: SSANGYONG TIVOLI

1.6G XLV(A) E4

Chassis No: KPT36BIVSHP149646

Engine No: 17391002081318

Reg.Date: 04/04/2017

Estimate Repair Cost to Vehicle No :

NO.	Description	Quantity	List Price	Amount
			\$\$	\$\$
1	REAR BUMPER <i>de</i>	1	\$ 912.75	\$ 912.75
2	REAR BUMPER REINFORCEMENT	1	\$ 529.68	\$ 529.68
3	REAR BOOT <i>X</i>	1	\$ 1,971.80	\$ 1,971.80
4	REAR END PANEL <i>X</i>	1	\$ 880.00	\$ 880.00
5	REAR END PANEL TOP GARNISH <i>X</i>	1	\$ 190.00	\$ 190.00
Total				\$ 4,484.23
Less 10%				\$ 448.42
Total				\$ 4,035.80

Paul

Hp 9006068

3 days

L/S

31/03/23 @ 1220

Resy after repair

	<u>SPECIAL NETTS</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	BUMPER CLIPS <i>m</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
Total				\$ 50.00

LABOUR CHARGES

1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS	\$	1,200.00 <i>400</i>
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND AFFECTED AREA.	\$	750.00 <i>450</i>
3	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	\$	120.00 <i>40</i>
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	\$	120.00 <i>X</i>
TOTAL		\$	2190.00
TOTAL PARTS		\$	4035.80
GRAND TOTAL		\$	6225.80

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

438D

Vehicle Details

Vehicle No.:

SLM6282C

Vehicle to be Exported:

No

Intended Deregistration Date:

02 Apr 2023

Vehicle Make:

SSANGYONG

Vehicle Model:

TIVOLI XLV 1.6G 6AT 2WD ESP E4

Primary Colour:

Red

Manufacturing Year:

2017

Engine No.:

17391002081318

Chassis No.:

KPT36B1VSHP149646

Maximum Power Output:

94.1 kW (126 bhp)

Open Market Value:

\$18,764.00

Original Registration Date:

04 Apr 2017

First Registration Date:

04 Apr 2017

Transfer Count:

0

Actual ARF Paid:

\$18,764.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

03 Apr 2027

PARF Rebate Amount:

\$13,134.00

Intended COE Rebate Details

COE Expiry Date:

03 Apr 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$49,430.00

COE Rebate Amount:

\$19,785.00

Total Rebate Amount:

\$32,919.00

Ssangyong Tivoli XLV 1.6A

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[M](#)**Price****\$65,300****Depreciation** ⓘ

\$13,940 /yr

[View models with similar depre](#)**Reg Date**

22-Feb-2017

(3yrs 10mths 19days COE left)

Mileage

82,000 km (13.4k /yr)

Manufactured ⓘ

2017

Road Tax ⓘ

\$1,182 /yr

Transmission

Auto

Dereg Value ⓘ\$34,206 as of today ([change](#))**Fuel Type**

Diesel

(Euro 5 Engine and Above)

COE ⓘ

\$50,991

OMV ⓘ

\$21,488

Engine Cap

1,597 cc

ARF

\$22,084

Curb Weight ⓘ

1,500 kg

Power

84.6 kW (113 bhp)

Type of Vehicle

SUV

No. of Owners

2