



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI23003399/Kvp3m4	
			Date: 17/04/2023	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 5288J	Veh. Inspected	SNG 1638B	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D00142304	Excess (\$)	0.00	
Assign From	KATIE LEE	Assign Date	31/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT SCENIC (A)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VF1RFA00361137060	Colour	METALLIC DARK BLUE	
Odometer	84761 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55R20	TRIANGLE	8 mm	
L/H Front Tyre	195/55R20	TRIANGLE	8 mm	
R/H Rear Tyre	195/55R20	TRIANGLE	9 mm	
L/H Rear Tyre	195/55R20	TRIANGLE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/03/2023	Inspection Date	10/04/2023	
Survey held at	ASTUTE AUTOWORKS PTE LTD 60 JALAN LAM HUAT, #02-16/17, CARROS CENTRE SINGAPORE 737869			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4.500 Working Days	