

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	INCOME INSURAN	ICE LTD		Ref:	CS3/INC22009015/Dvp3m4-1	
	75 BRAS BASAH R INCOME CENTRES	ROAD SINGAPORE 189557		Date:	05/04/2023	
	ATTN: MARCUS X	IAO		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFM 8008L	Veh. Inspected		SMY 7588P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1187972-002	Excess (\$)		0.00	
	Assign From		Assign Date		31/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	JM6BP2SAAM1107120	Colour		WHITE	
	Odometer	120251 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	GRENLANDER		6 mm	
	L/H Front Tyre	205/60 R16	GRENLANDER		6 mm	
	R/H Rear Tyre	205/60 R16	GRENLANDER		6 mm	
	L/H Rear Tyre	205/60 R16	GRENLANDER		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	08/09/2022	Inspection Date	е	13/09/2022	
	Survey held at	D'S GRAFFITI CONCEPTS PTE	LTD			
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				