

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: PC 4392Lat Workshop m/s R & S ENGINEERINGof 13, HONGKONG SECTOR 1Insured: H5B

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 41K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Ltm Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PC 4392L Yr Regn: 2015 DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HIACE COM MAN c.c. 2982Colour: GREEN A/C: Insured / Std / NI / NASp. Reading: 177449 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFJ T02P X00001721

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FAUKEW

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 30/03/23D.O.I. 04/04/23Survey held at R & S

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 32K

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report1) _____
Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

PC4392L

TP INSURER :	<u>HSBC life (S) Pte Ltd</u>
OWN INSURER :	<u>Income Insurance Ltd</u>
CLAIM TYPE :	<u>TP</u>
Date of Accident :	<u>30/3/2023</u>

COST OF CLAIMS

This claim is handled by : **MINOKO**

Vehicle Reg. No. : **PC4392L**
 Vehicle Reg. Date: **1/12/2015**
 Make / Model : **TOYOTA HIACE COMMUTERMANUAL**
 Engine No. : **1KD2455125**
 Chassis No. : **JTFJT02PX00001721**

PAGE 1

Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR QUARTER PANEL RH <i>repair</i>		\$ 2,596.00		
2	1	REAR QUARTER WINDOW ASSY RH <i>SA</i>		\$ 3,596.00		
3	1	REAR QUARTER PANEL GLASS SEALANT RH <i>X</i>		no use		
4	1	REAR QUARTER INNER TRIM BOARD RH <i>X</i>		\$ 195.00		
5	1	REAR QUARTER INNER TRIM BOARD CLIPS RH <i>X</i>		\$ 180.00		
6	1	ROOF CHANNEL DRIP RH <i>X</i>		\$ 494.00		
7	1	TAILLAMP RH <i>SA</i>		\$ 300.00		
8	1	TAILLAMP CLIPS RH <i>me</i>		\$ 10.00	30	
9	1	TAILLAMP GASKET RH <i>X</i>		with taillamp		
10	1	REAR BUMPER <i>X</i>		\$ 415.00		
11	1set	REAR BUMPER CLIPS <i>X</i>		\$ 50.00		
12	1	REAR BUMPER SIDE RETAINER RH <i>X</i>		\$ 65.00		
13	1	REAR UPPER BUMPER COVER CLIPS RH <i>X</i>		\$ 111.00		
14	1	REAR UPPER BUMPER SIDE BRACKET RH <i>X</i>		\$ 65.00		
15	1set	REAR UPPER BUMPER COVER CLIPS RH <i>X</i>		\$ 50.00		
16	1	PRIVATE BUS STICKER RH <i>SA</i>			\$ 80.00	20
17	0	0				
18	0	0				
19	0	0				
20	0	0				
21	0	0				
22	0	0				
23	0	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Vehicle Reg. No. :	PC4392L
Vehicle Reg. Date:	1/12/2015
Make / Model :	TOYOTA HIACE COMMUTERMANU.
Engine No. :	JTFJT02PX00001721
Chassis No. :	#REF!

PAGE 1

Labour

[illegible]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2nd
 Hp 90010068
 3 ~~days~~
 7/18
 04/04/23 @ 0900
 Raising after repair

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 680K

Vehicle Details

Vehicle No.: PC4392L

Vehicle to be Exported: No

Intended Deregistration Date: 05 Apr 2023

Vehicle Make: TOYOTA

Vehicle Model: HIACE COMMUTER MANUAL

Primary Colour: Silver

Manufacturing Year: 2014

Engine No.: 1KD2455125

Chassis No.: JTFJT02PX00001721

Maximum Power Output: -

Open Market Value: \$35,969.00

Original Registration Date: 01 Dec 2015

First Registration Date: 01 Dec 2015

Transfer Count: 0

Actual ARF Paid: \$1,799.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Nov 2025

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

POP Paid: \$31,758.00

COE Rebate Amount: \$8,424.00

Total Rebate Amount: \$8,424.00

Toyota Hiace Commuter 3.0A

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price

\$39,800

Lifespan ⓘ

11-Oct-2035

Depreciation ⓘ

\$15,790 /yr

[View models with similar depre](#)

Reg Date

12-Oct-2015

(2yrs 6mths 6days COE left)

Mileage

N.A.

Manufactured ⓘ

2015

Road Tax ⓘ

N.A.

Transmission

Auto

Dereg Value ⓘ

\$1,290 as of today ([change](#))

Fuel Type

Diesel

COE ⓘ

\$5,116

OMV ⓘ

\$36,257

Engine Cap

2,982 cc

ARF ⓘ

\$1,813

Curb Weight ⓘ

1,980 kg

No. of Owners

2