

REF:

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its repair at the time of inspection.

	
N/S	O/S

Bal. or Market Value:	_____		
IDAC Accident Rpt:	_____	Consistent? :	Yes or No
GIA / PR Seen:	_____	Consistent? :	Yes or No
Est. Repairs:	_____ days	Res.:	Yes or No
Lum Sum:	_____ %	3 Val.:	Yes or No

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GU3232J Yr Regn: 2008 / Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Pick Up.

Make: Isuzu TFR86 C.C. 2499.

Colour: Blue. A/C: Insured / Std / NI / NA

Sp. Reading: 524282 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MPATFR86H7H586440

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 215/65R15

R: 215/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken.

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 27/03/23

*Survey held at YSK.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Union
	COE Expiry: 31/12/27.
	MV :
	PV :
	Nett :
	266D

☐ : Prel. Report
☐ : Final Report

1980年2月6日

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$) _____
☐ : Interview (\$) _____
☐ : Tech. Invs (\$) _____
☐ : _____ (\$ _____)

Others

A blank sheet of white paper with horizontal blue ruling lines. The left edge shows a dark binding strip. There are five visible lines across the page.