



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile               |                                                                                                                                        |                                                                 |                            |            |
|---------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------|----------------------------|------------|
| TAN CHIN HOE & CO<br>24 RAFFLES PLACE<br>#24-01 CLIFFORD CENTRESINGAPORE 048621 |                                                                                                                                        |                                                                 | Ref: CS/LAW23003422/Uvy3e2 |            |
|                                                                                 |                                                                                                                                        |                                                                 | Date: 27/04/2023           |            |
|                                                                                 |                                                                                                                                        |                                                                 | Code: L128                 |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>         |                                                                                                                                        |                                                                 |                            |            |
|                                                                                 | Insured Veh.                                                                                                                           | SLD 7532Y                                                       | Veh. Inspected             | FBS 4950H  |
|                                                                                 | Policy No.                                                                                                                             |                                                                 | Coverage (\$)              | 0.00       |
|                                                                                 | Claim No.                                                                                                                              | RT/CT/17/2023/gn                                                | Excess (\$)                | 0.00       |
|                                                                                 | Assign From                                                                                                                            | KIRAN KAUR                                                      | Assign Date                | 24/03/2023 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                   |                                                                                                                                        |                                                                 |                            |            |
|                                                                                 | Make & Model                                                                                                                           | YAMAHA MTN 155                                                  | c.c                        | 155        |
|                                                                                 | Engine No.                                                                                                                             | HIDDEN                                                          | Year of Reg.               | 2021       |
|                                                                                 | Chassis No.                                                                                                                            | MH3RG711000001146                                               | Colour                     | WHITE      |
|                                                                                 | Odometer                                                                                                                               | 4833 KM                                                         | Steering                   | IN ORDER   |
|                                                                                 | Brakes                                                                                                                                 | IN ORDER                                                        | Modification               | SPORTS RIM |
|                                                                                 | General                                                                                                                                | GOOD                                                            |                            |            |
| <b>3. Conditions of Tyres</b>                                                   |                                                                                                                                        |                                                                 |                            |            |
|                                                                                 |                                                                                                                                        | Size                                                            | Make                       | Balance    |
|                                                                                 | R/H Front Tyre                                                                                                                         | 110/70 R17                                                      | IRC                        | 7 mm       |
|                                                                                 | L/H Front Tyre                                                                                                                         |                                                                 |                            | mm         |
|                                                                                 | R/H Rear Tyre                                                                                                                          | 140/70 R17                                                      | IRC                        | 7 mm       |
|                                                                                 | L/H Rear Tyre                                                                                                                          |                                                                 |                            | mm         |
| <b>4. Description of Damages</b>                                                |                                                                                                                                        |                                                                 |                            |            |
|                                                                                 | THE MOTORCYCLE HAD COMPLETED ITS REPAIR WORKS.<br>REPAIR CONDITION SEE DETAILS.                                                        |                                                                 |                            |            |
| <b>5. General Information</b>                                                   |                                                                                                                                        |                                                                 |                            |            |
|                                                                                 | Accident Date                                                                                                                          | 16/04/2022                                                      | Inspection Date            | 06/04/2023 |
|                                                                                 | Survey held at                                                                                                                         | HL CYCLE PL<br>1 KAKI BUKIT AVE 6<br>#02-58<br>SINGAPORE 417883 |                            |            |
| <b>5a. Remarks</b>                                                              |                                                                                                                                        |                                                                 |                            |            |
|                                                                                 | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                 |                            |            |
| <b>5b. Estimate Days of Repair</b>                                              |                                                                                                                                        |                                                                 |                            |            |
|                                                                                 | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                 | 6 Working Days             |            |