

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 23.03.2023

INSURANCE: CHINA

MODEL: Mercedes W212/E220

MVA: CHIANG

VEHICLE NO.: SHA7455A

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1	Bumper Assy, Frt			Ry \$1,890.50
1	Bumper Bracket, Frt/RH			\$95.00
1	Front Fender LH			bl- \$996.08
1	Front Fender Shield LH			tn? \$257.00
1	Front Mirror Housing W/signal LH			cut- \$890.00
1	Front Mirror Motor Assy			x \$920.00
1	Front Mirror Cover			cut- \$350.00
	SUB TOTAL			\$5,398.58
	LESS 20%			\$1,079.71
	DISCOUNTED TOTAL			\$4,318.64
	SUB TOTAL			\$-
	<u>Labour Charge</u>			
	Panel Beating			400 \$800.00
	Spray Painting Charge			750 \$800.00
	Wiring Charge		1180	30 \$60.00
	TOTAL LABOUR			\$1,660.00
	ESTIMATE TOTAL			\$5,978.64
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphu 97495749
 WP 23/3/23C 415m
 4/3 Resurvey after repair
 2 days - 3 days
 Tanphu@lhaat.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

for:

A member of COMFORTDELGRO

Date/Time: 23.03.2023 15:42

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5890583

JC NO305549535

ISTOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)
(P)

REGN NO.

SHA7455A

MILEAGE

MAKE

MERCEDES BENZ

FUEL

E.....1/2.....F

MODEL

E220CDI(E6)

DATE/TIME IN

23.03.2023 12:15

YR OF MANU

28.05.2015

TARGET DATE

CHASSIS CODE

WDD2120012B177625

COMPLETION DATE/TIME:

SCOUNT CARD NO.


JOB DESCRIPTION

Ident Date: 23.03.2023
NATURE: 3P 23.03.2023

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

e:

lo.:

le No.:

SHA7455A

CHIANG

Exit Pass

Vehicle No.:

SHA7455A

ie of Service Advisor

Signature/Date

Name of Service Advisor

Date

e returned to Service Reception upon collection

To be kept by Security Guard