

(08/11/13) wef

ASS. REC. BY

REF:

CS/FCI 23003439/Rgy3m4

316M

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: SNO 69974

at Workshop m/s PERFORMANCE

of ALEXANDRA RD

Insured: FCI

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 165K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lim Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SNO 69974

Yr Regn: 2022 JPN

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 218IACMSPTHL c.c 1499

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 13149 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA12AK090 7K41268

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 31/03/23

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FCT

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 03/04/23

PERFORMANCE

Date / Time Action / Instruction

REPAIR LIMIT - 65K

Rasul finalised final fig \$2132.70, 1 day. (Red \$38, 2%)

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

110

Transportation:

50

S + RS SI

50

Photos

23

Others

TOTAL

233

Report Format: TP

Lump Sum / I.B.I: (\$ 2132.70)