

(08/11/13) wef

ASS. REC. BY:

REF:

CS/FCI 23003439/R9y3

316M

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: SNO 69974

at Workshop m/s PERFORMANCE

of ALEXANDRA RD

Insured: FCI

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 165K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SNO 69974

Yr Regn: 2022 JMW

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 218IACMSPTHL c.c 1499

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 13149 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA12AK090 7K41268

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 31/03/23

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FCT

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 03/04/23

PERFORMANCE

Date / Time Action / Instruction

REPAIR LIMIT - 65K

Rasul finalised final fig \$2132.70, 1 day. (Red \$38, 2%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ 2132.70)

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

31 MAR 2023

ESTIMATE

Estimate No. : b1 65495
Date Estimated : 31/03/2023
Prepared By : Jack Ng Guo Ming

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Bannak Mudiyansele Sandun Champik
16 Tanah Merah Kechil Link
#14-33

Singapore 465424

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND6997Y	WBA12AK0907K41268	20/01/2022	218i Gran Coupe	7804

DESCRIPTION

To remove and replace left wing mirror.

To check electrical wiring

To respray left wing mirror cap

VALUE

403 480.00

168 17.00

70 74.00

Total Labour 1: 701.00

DESCRIPTION

LH OUTSIDE MIRROR HEATED WITH MEMOR

LH MIRROR GLASS HEATED WIDE ANDLE

LH OUTSIDE MIRROR COVER CAP PRIMED

QTY

PRIC

VALUE

1 859.90

1 435.90

1 133.90

859.90

435.90

133.90

Total Parts : 1,429.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No.

Claim No.

Date&Time

03/04/23 @ 1220

Excess S\$

Surveyor's Name

PML

Sign

Surveyor's Tel

90010068

Authorised Yes / No

Authorised Date

Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommended

1 day

Labour 1

701.00

Parts

1,429.70

Labour 2

0.00

Excess

0.00

Total GST @ 8%

170.46

Grand Total

2,301.16



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Foreign Identification Number

Owner ID:

316M

Vehicle Details

Vehicle No.:

SND6997Y

Vehicle to be Exported:

No

Intended Deregistration Date:

03 Apr 2023

Vehicle Make:

B.M.W.

Vehicle Model:

218i GC MSPT, LED HL, FL

Primary Colour:

Black

Manufacturing Year:

2021

Engine No.:

35776548B38A15F

Chassis No.:

WBA12AK0907K41268

Maximum Power Output:

100.0 kW (134 bhp)

Open Market Value:

\$36,054.00

Original Registration Date:

20 Jan 2022

First Registration Date:

20 Jan 2022

Transfer Count:

0

Actual ARF Paid:

\$42,476.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

19 Jan 2032

PARF Rebate Amount:

\$31,857.00

Intended COE Rebate Details

COE Expiry Date:

19 Jan 2032

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$77,700.00

COE Rebate Amount:

\$68,321.00

Total Rebate Amount:

\$100,178.00

BMW 2 Series 218i Gran Coupe M-Sport

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)**Price****\$149,000****Depreciation** ⓘ

\$16,400 /yr

[View models with similar depre](#)**Reg Date**

15-Jan-2021

(7yrs 9mths 11days COE left)

Mileage

40,000 km (18.1k /yr)

Manufactured ⓘ

2020

Road Tax ⓘ

\$684 /yr

Transmission

Auto

Dereg Value ⓘ\$70,252 as of today ([change](#))**OMV** ⓘ

\$36,049

COE ⓘ

\$49,300

ARF ⓘ

\$42,469

Engine Cap

1,499 cc

Power

103.0 kW (138 bhp)

Curb Weight ⓘ

1,375 kg

No. of Owners ⓘ

3

Type of Vehicle[Luxury Sedan](#)