ASS. FEO.BY: CS/FCI2	23003449/Aqy3
AS	SIGNMENT
From 2 Date:	Veh No: SML8547U. Yr Regn: 2019, June
Estima ated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To In≲ped Vehicle No:	Make: Honde Vezel c.c 1496.
at Workshop m/s	Colour Ryple A/C: Insured / Std / NI / NA
of	Sp.Reading 73184. T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: RU11314046 *
Claims No.	Gen. Cond: Sood Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Increar / Jammed / Leaked / Burnt or
Make of Veh:	Modí: Nil S/Rim STD A/Rim or
	Tyre Size: F: 215/60R16
(Policy Condition)	R: 215/60P16
Remark: The veh had commenced its N/S O/S	BS / DÚN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO OF
Bal, or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 06 mm L/Bal. 96 mm
Est. Repairs: 6 days Res.: Yes or No	D.O.A. D.O.I. 03/04/23.
Lum Sum: % 3 Val.: Yes or No	'Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / On Date: Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
TP 18 Cop.	
LS \$5150, 6 days (Red \$3833.12,	43%)
mv :	
PV ;	
Nett:	
	200 - ,
	399 N.
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 6
1) 10/04 Typist : Final Report	Resurvey No. of Trip: 2 Survey Fee:
Date/Time, File Return to?	Transportation:
Add F	
Person Former TP	: Interview (\$) Photos

Bernin Frem 18 P 1: 72