ASS. REC BY: REF: CS/FCI23003449/Aqy3

ASSIGNMENT

From : Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMB5474U. Yr Regn: 2019, June.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Vezel c.c 1496.

Colour Purple. A/C: Insured / Std / NI / NA

Sp.Reading 73184. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU113140 46 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16.

R: 215/60R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	03/04/23.

Survey held at Ryder.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.
	LS $5150, 6 days (Red $3833.12, 43%)
	MV :
	PV :
	Nett :
	399 N.

Date/Time, File Pass to? ☐ : Preli. Report

1) 10/04 Typist ☐ : Final Report

Date/Time, File Return to?

2)

Report Format : TP

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

Survey Fee:	160
Transportation:	50
___S + RS.___SI	50+50
Photos	77
Others	
	387