

ASS. REC. BY:

REF: CTZ/2300-34911kv

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GBL 9170X

Policy No. DMCVSNW00090702200

Claims No. SNM23D201748/C02/TOHHS

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 840k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 08 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 2H NOT ready

29/5/23 11:30 857000 Cash (red 2318.30, 28%)

Veh No: GBD 953014

Yr Regn: 08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Dyna

c.c. 2982

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 340585

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: K0Y231

8018PT9

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Mic

195R15X8

Gratade 155R12X8(10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mm

R/Bal. 99 mm

L/Bal. 9 mm

L/Bal. 99 mm

D.O.A. 6/3/23

D.O.I. 28/3/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s, o/s Fr & Fr N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format: Merimen

Lump Sum / +B. (\$ 5700)

> Back to OneMotoring

GBD9530H
7P/C4/MH

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	433E

Vehicle Details

Vehicle No.:	GBD9530H
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Mar 2023
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2490882
Chassis No.:	KDY2318018979
Maximum Power Output:	-
Open Market Value:	\$29,259.00
Original Registration Date:	03 Aug 2015
First Registration Date:	03 Aug 2015
Transfer Count:	1
Actual ARF Paid:	\$1,463.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	02 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$21,354.00
COE Rebate Amount:	\$5,011.00
Total Rebate Amount:	\$5,011.00

The information contained herein is correct as at 28 Mar 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/03/2023 16:52 (SGT)
Reported by	Driver
Date of Accident	06/03/2023 13:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SEMBAWANG RD (LAMP POST 142)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD9530H
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	KEYSTONE CRAFT PTE LTD
Company Reg No	2XXXXX433E
Email Address	themandy96@gmail.com
Mobile Phone No	(Phone) +65-81249439
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNW0009222201

DRIVER

Name of Driver	ANG TIONG AIK
NRIC No	SXXXX034G
Date Of Birth	10/07/1950
Occupation	Outdoor

Date Of Driving Pass	17/03/1972
Driving experience	51 YEARS
Gender	Male
Mobile Number	(Phone) +65-96975963
Alt. Phone Number	-
Email Address	angtiongaik@gmail.com
Address	BLK 326 ANG MO KIO AVE 3 #05-1990
Address complement	-
Postcode	560326
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Ang Mo Kio South Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004519999
Alt. Police Station Phone No	(Fax) +65-65535679
Police Station Address	81 Ang Mo Kio Ave 3 Singapore 569929
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBL9170X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	JASON
Contact Number	(Phone) +65-93891861
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMN6769Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	SIM YAO TUAN
NRIC No	SXXXX729D
Contact Number	(Phone) +65-94509008
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Government
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	ROADSIDE BARRIER FENCE
No. Of Passenger (Including Driver)	-

SKETCH PLAN

VEH NO: 98D9530H
INSURER: China
DATE OF ACC: 06/03/23 @ 13.50

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

07/03/23
[Signature]

Sketch Plan

PLEASE
TURN
OVER

Describe Circumstance of the Accident

** NOTE: PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

() Claim Own Policy (☒) Claim Third party () Reporting Only

() Claim OD/ TP at other workshop ()

Sketch Plan

roadside barrier fence

Sembawang Rd (Lamp post 142)

pavement

grass patch

A: 9BD 9530H (alone)

B: 9EL 9170X (alone)
JASON-93891661

C: SMN 6769Z
Sim Yau Tuan (alone)
SEI 267290
Hp: 94509008

Vehicle No: 9BD 9530H (Honda)

Date & Time: 06/03/23 @ 1350 (clear/dry)

Refer to police report.

(came to a back impact)

P/S: my lorry had went up the side Kerb, onto a grass patch, pavement & hit onto a roadside barrier fence before it came to a halt.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

[Signature]

Witnessed by Reporting Centre Personnel (Name as in NRIC card)

(AMK)

GBD 9530 H

1 pc tail gate ✓

Stroke DYNA ✓

Stroke 1500 Kg ✓

R/H lock handle ✓

R/H safety lock ✓

R/H hinge ✓

1 pc R/H tail lamp ✓

panel ✓

1 pc rear reflector ✓

1 pc L/H tail lamp ✓

1 pc R/H side gate ✓

1 pc fit bumper ✓

4H bracket ?

4H fog lamp ?

4H fog lamp garnish ?

1 pc for 4H corner panel ✓

garnish ?

GRD 9530 H

1 pc LH head lamp ✓

1 pc air con condenser ?
fan

1 pc LH door rx

1 pc LH panel sticker 'DYNA' ✓

1 pc RH head lamp ✓

1 pc LH RH door lamp ✓

GBH 9530H

2 m to door coy sticks

1 m to km/h sticks

1 m 13 120x sticks

1 m tail gate inner protect

1 m R/L railing

\$20 x 2 = \$40 / sn ✓

\$10 / sn ✓

\$10 / sn ✓

\$350 / sn ✓

\$350 / sn ✓

GBD 9530 H

① R & R tail gate assy, R/H side gate,

To K&R cabin rear R/H pillar, ftr panel, ftr R/H
door, rear truck end member, R/H side
member and realign rear truck position 1100/-
#1200/✓

② Putty & respray on ftr panel, ftr both doors,
tail gate, R/H side gate, lower members,
cabin rear R/H pillar,

1350/-
#1500/✓

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Mar 2023)
 Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for GBD9530H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Att MR. Kenneth

GBD 9530H

TP/CATINA

Estimates on Parts

No. Qty Part No. Particulars

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC TAILGATE	0.00	0.00	Ry *550.00 F
2	1		*1 PC TAILGATE STICKER (DYNA)	0.00	0.00	Ry *20.00 F
3	1		*1 PC TAILGATE STICKER (1500 KG)	0.00	0.00	Ry *30.00 F
4	1		*1 PC TAILGATE RH LOCK HANDLE	0.00	0.00	Ry *55.00 F
5	1		*1 PC TAILGATE RH SAFETY LOCK	0.00	0.00	Ry *40.00 F
6	1		*1 PC TAILGATE RH HINGE	0.00	0.00	Ry *52.00 F
7	1		*1 PC RH TAILLAMP	0.00	0.00	Ry *105.00 F
8	1		*1 PC RH TAILLAMP PANEL	0.00	0.00	Ry *48.00 F
9	1		*1 PC REAR REFLECTOR	0.00	0.00	Ry *28.00 F
10	1		*1 PC LH TAILLAMP	0.00	0.00	Ry *105.00 F
11	1		*1 PC RH SIDE GATE	0.00	0.00	Ry *650.00 F
12	1		*1 PC FRT BUMPER	0.00	0.00	Ry *220.00 F
13	1		*1 PC FRT BUMPER LH BRACKET ?	0.00	0.00	Ry *105.00 F
14	1		*1 PC FRT BUMPER LH FOG LAMP ?	0.00	0.00	Ry *100.00 F
15	1		*1 PC FRT BUMPER LH FOG LAMP GARNISH ?	0.00	0.00	Ry *60.00 F
16	1		*1 PC FRT LH CORNAL PANEL	0.00	0.00	Ry *90.00 F
17	1		*1 PC FRT LH CORNAL GARNISH ?	0.00	0.00	Ry *50.00 F
18	1		*1 PC LH HEADLAMP	0.00	0.00	Ry *300.00 F
19	1		*1 PC AIR-CON CONDENSER ?	0.00	0.00	Ry *450.00 F
20	1		*1 PC FRT LH DOOR	0.00	0.00	Ry *620.00 F
21	1		*1 PC FRT PANEL STICKER (DYNA)	0.00	0.00	Ry *30.00 F
22	1		*1 PC RH HEADLAMP	0.00	0.00	Ry *300.00 F
23	1		*1 PC FRT RH DOOR LAMP	0.00	0.00	Ry *45.00 F

F=Franchise part.

Sub Total (\$\$) 4,053.00

+ Margin on L,N Items 10.00% (\$\$) 405.30

Total Parts (\$\$) 4,458.30

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	1 PC RH RAILING	Ry 350.00
2	1	1 PC STICKER - 13 PAX	Ry 10.00
3	1	1 PC STICKER - 70KM/H	Ry 10.00
4	1	1 PC TAILGATE INNER PROTECTOR	Ry 350.00
5	1	2 PCS FRT DOOR COY STICKERS @20/PC	Ry 40.00

Sub Total (\$\$) 760.00

Estimates on Labour

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No	Particulars	Lab.Type	Amount	
<u>Labour Items</u>				
1	REMOVE & REFIX TAILGATE ASSY, RH SIDE GATE, TO KNOCK & REPAIR CABIN REAR RH PILLAR, FRT PANEL, FRT RH DOOR, REAR TRUCK END MEMBER, RH SIDE MEMBER AND REALIGN REAR TRUCK POSTION.	New	1,200.00	1100
2	PUTTY & RESPRAY ON FRT PANEL, FRT BOTH DOORS, BOTH HEADLAMPS ETC, TAILGATE, RH SIDE GATE, LOWER MEMBER, CABIN REAR RH PILLAR	New	1,500.00	1300 1350
3	REMOVE & REFIX AIR-CON, CHECK, VACUUM & REFILL GAS	New	100.00	✓
Gross Labour Cost (S\$)			2,800.00	

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >

Parts #3118
Less 20% 623.60
\$2494.40
690 Sd
\$2550
\$5234.40
43 \$5730