

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                            |                                                    | Reg. No: 199607                                                                                                                        | 198R GST Reg. No. 19   | -96071 | 98-R                  |  |
|--------------------------------------------|----------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|------------------------|--------|-----------------------|--|
|                                            |                                                    | Affiliated to Federation Internation                                                                                                   | nale Des Experts En Au | utomok | pile                  |  |
|                                            | AUTO & GENERA                                      | L INSURANCE (S) PL                                                                                                                     | Re                     | ef:    | CS/AGI23003503/Any3e2 |  |
|                                            |                                                    | INSURANCE)<br>U AVENUE #03-01<br>PPING CENTRESINGAPORE                                                                                 | Da                     | ate:   | 20/07/2023            |  |
|                                            |                                                    |                                                                                                                                        | Co                     | ode:   | AGI                   |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM |                                                    |                                                                                                                                        |                        |        |                       |  |
|                                            | Insured Veh.                                       | SMD 5015A                                                                                                                              | Veh. Inspected         |        | SMW 9772X             |  |
|                                            | Policy No.                                         | P10332847R03                                                                                                                           | Coverage (\$)          |        | 0.00                  |  |
|                                            | Claim No.                                          | C10021392 /CD                                                                                                                          | Excess (\$)            |        | 0.00                  |  |
|                                            | Assign From                                        | FRAULEINE KHOO                                                                                                                         | Assign Date            |        | 04/04/2023            |  |
| 2. Vehicle Particulars & Condition         |                                                    |                                                                                                                                        |                        |        |                       |  |
|                                            | Make & Model                                       | SSANGYONG TIVOLI                                                                                                                       | c.c                    |        | 1597                  |  |
|                                            | Engine No.                                         | HIDDEN                                                                                                                                 | Year of Reg.           |        | 2020                  |  |
|                                            | Chassis No.                                        | KPT30A1USLP318074                                                                                                                      | Colour                 |        | BLUE                  |  |
|                                            | Odometer                                           | 58433 KM                                                                                                                               | Steering               |        | IN ORDER              |  |
|                                            | Brakes                                             | IN ORDER                                                                                                                               | Modification           |        | SPORTS RIM            |  |
|                                            | General                                            | GOOD                                                                                                                                   |                        |        |                       |  |
| 3.                                         | Conditions of Tyres                                |                                                                                                                                        |                        |        |                       |  |
|                                            |                                                    | Size                                                                                                                                   | Make                   |        | Balance               |  |
|                                            | R/H Front Tyre                                     | 205/65 R16                                                                                                                             | MICHELIN               |        | 6 mm                  |  |
|                                            | L/H Front Tyre                                     | 205/65 R16                                                                                                                             | MICHELIN               |        | 6 mm                  |  |
|                                            | R/H Rear Tyre                                      | 205/65 R16                                                                                                                             | MICHELIN               |        | 6 mm                  |  |
|                                            | L/H Rear Tyre                                      | 205/65 R16                                                                                                                             | MICHELIN               |        | 6 mm                  |  |
| 4.                                         | Description of Damages                             |                                                                                                                                        |                        |        |                       |  |
|                                            | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. |                                                                                                                                        |                        |        |                       |  |
|                                            | DAMAGES SEE DETAILS.                               |                                                                                                                                        |                        |        |                       |  |
| 5.                                         | General Information                                |                                                                                                                                        |                        |        |                       |  |
|                                            | Accident Date                                      | 30/03/2023                                                                                                                             | Inspection Date        |        | 04/04/2023            |  |
|                                            | Survey held at                                     | rvey held at TK LEE AUTOMOTIVE PTE LTD                                                                                                 |                        |        |                       |  |
|                                            |                                                    | NO. 1 KAKI BUKIT AVE 6<br>#02-47 AUTOBAY<br>SINGAPORE 417883                                                                           |                        |        |                       |  |
| 5a.                                        | a. Remarks                                         |                                                                                                                                        |                        |        |                       |  |
|                                            | A)THE INSPECTION                                   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                        |        |                       |  |
| 5b.                                        | D)III / IOOORDAIN                                  | Estimate Days of Repair                                                                                                                |                        |        |                       |  |
|                                            |                                                    |                                                                                                                                        |                        |        |                       |  |

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: