

Our Job Ref No : 305550436Date : 24.04.2023ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969**FINALIZATION FORM**To : LKK

Fax :

Attn : TAUFIKH NAZVehicle Reg No. : SH9185Z01.04.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: INCOME XD9733D
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** _____
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$7,500.00

3. Estimated normal period for repairs: 7.8 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Name : CHIANGTel : 62148314Fax : 65468156Signature : Name : NAZ LKKDate : 1/6/2023**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$26.75/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

At 2 level

VEHICLE NO	SH9185Z
MAKE	22.12.2016
MODEL	I-40

CHIANG/ INCOME

[illegible]

	ESTIMATE TOTAL	10,679.82 8,543.62	\$18,940.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

NA2 UKK
3/4/2023 1645
LIS
6 DAYS
(CHECK ITEM PHOTO)
AFTER REPAIR PHOTO -
* request book value.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: