

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19-	9607198-R	
		Affiliated to Federation Internation	nale Des Experts En Au	tomobile	
	AUTO & GENERA	L INSURANCE (S) PL	Re	f: CS/AGI23003549/Uny3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	te: 18/04/2023	
			Co	de: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMJ 5689Z	Veh. Inspected	SMC 7107K	
	Policy No.	P10331688R03	Coverage (\$)	0.00	
	Claim No.	C10021519/CD	Excess (\$)	0.00	
	Assign From	DON BONG	Assign Date	05/04/2023	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA INTEGRA 2.0M (M)	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2006	
	Chassis No.	JHMDC53506S200527	Colour	BLACK	
	Odometer	313113 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/40Z R17	MICHELIN	7 mm	
	L/H Front Tyre	245/40Z R17	MICHELIN	7 mm	
	R/H Rear Tyre	245/40Z R17	MICHELIN	7 mm	
	L/H Rear Tyre	245/40Z R17	MICHELIN	7 mm	
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/04/2023	Inspection Date	05/04/2023	
	Survey held at HANIP AUTOMOBILES ENGINEERING				
		NO 1 KAKI BUKIT AVE 6 #01-73 SINGAPORE 417883			
5a.	ia. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	DJIN ACCORDANG	Estimate Days of Repair			
0.0	Latinate Days of Nepan				

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: