ANYSIA FOO



MOTOR SURVEY ASSIGNMENT

Contact Person

Date 04/04/2023 **Our Ref No.** D23001159MFCV

Accident Date 31-03-2023 Claim Type Third Party

Insured Vehicle GBK2267C Third Party Vehicle SJX1800G

Survey Location HOCK WAH MOTOR

WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E BEDOK NORTH AVE 4 #01-2008/10/12 (S) 489977

Contact No. 64415655 **Fax No.**

Survey Type Without Prejudice

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person Fax No. 68416315

Contact Number 62563561

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & Estimate

Cc: Workshop HOCK WAH MOTOR WORKSHOP PTE LTD Attention ANYSIA FOO

Officer Incharge SITHARA

IMPORTANT NOTE

Kindly submit the survey report by **email only** to <u>surveyor@msfirstcapital.com.sg</u> within 14 days for survey assignment and 7 days for re-inspection.