



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23003572/Kny3e2	
			Date: 02/05/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJJ 7535G	Veh. Inspected	SLU 1162G
	Policy No.	D22MTPV01014405	Coverage (\$)	0.00
	Claim No.	CMTD2301355/THE	Excess (\$)	0.00
	Assign From	BETTY WONG	Assign Date	05/04/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDGG20W60J008303	Colour	METALLIC GREY
	Odometer	107704 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	MICHELIN	7 mm
	L/H Front Tyre	195/65 R15	MICHELIN	7 mm
	R/H Rear Tyre	195/65 R15	MICHELIN	7 mm
	L/H Rear Tyre	195/65 R15	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/04/2023	Inspection Date	06/04/2023
	Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	