

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|   | Reg. No: 19960/198R GST Reg. No. 19-960/198-R   |   |                 |       |                         |  |
|---|---|---|-----------------|-------|-------------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile |   |   |                 |       |                         |  |
|   | ALLIED WORLD A  | SSURANCE COMPANY LTD  | R               | Ref:  | CS3/AWA22002726/Rqy3e2- |  |
|   | (SINGAPORE BRA<br>60 ANSON ROAD<br>MAPLETREE ANS<br>SINGAPORE 079   | #08-01 (8th FLOOR)  | D               | Date: | 16/05/2023              |  |
|   |   |   |                 | Code: |                         |  |
| 1.  |   |   |                 |       |                         |  |
|   | Insured Veh.  | YQ 3819A  | Veh. Inspected  |       | SMW 6686G               |  |
|   | Policy No.  | BVFCSB0007242114  | Coverage (\$)   |       | 0.00                    |  |
|   | Claim No.   | NSV2200035/HLF  | Excess (\$)     |       | 0.00                    |  |
|   | Assign From   | HEW LEE FONG  | Assign Date     |       | 04/04/2023              |  |
| 2.  | 2. Vehicle Particulars & Condition  |   |                 |       |                         |  |
|   | Make & Model  | MERCEDES BENZ C180 AV   | c.c             |       | 1595                    |  |
|   | Engine No.  | HIDDEN  | Year of Reg.    |       | 2017                    |  |
|   | Chassis No.   | WDD2050402R252285   | Colour          |       | WHITE                   |  |
|   | Odometer  | 90503 KM  | Steering        |       | IN ORDER                |  |
|   | Brakes  | IN ORDER  | Modification    |       | SPORTS RIM              |  |
|   | General   | FAIR  |                 |       |                         |  |
| 3. Conditions of Tyres  |   |   |                 |       |                         |  |
|   |   | Size  | Make            |       | Balance                 |  |
|   | R/H Front Tyre  | 225/45 R18  | CONTINENTAL     |       | 6 mm                    |  |
|   | L/H Front Tyre  | 225/45 R18  | CONTINENTAL     |       | 6 mm                    |  |
|   | R/H Rear Tyre   | 225/45 R18  | CONTINENTAL     |       | 6 mm                    |  |
|   | L/H Rear Tyre   | 225/45 R18  | CONTINENTAL     |       | 6 mm                    |  |
| 4.  | Description of Damages  |   |                 |       |                         |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  |   |                 |       |                         |  |
|   | DAMAGES SEE D   | DAMAGES SEE DETAILS.  |                 |       |                         |  |
| 5.  | General Information   |   |                 |       |                         |  |
|   | Accident Date   | 18/03/2022  | Inspection Date |       | 28/03/2022              |  |
|   | Survey held at  | Survey held at REVOL CARZ GARAGE PTE LTD  BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047 |                 |       |                         |  |
|   |   |   |                 |       |                         |  |
| 5a.   | Remarks   |   |                 |       |                         |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |       |                         |  |
| 5b.   |   | Estimate Days of Repair   |                 |       |                         |  |

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: