

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305550780
Date : 11.04.2023

FINALIZATION FORM

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHA1539G

Date of Accident : 04.04.2023

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME -- SLZ9719Y

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges (include advertisement stickers etc, if any)

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

~~\$4,350.00~~ \$4,800.00
~~\$4,350.00~~ \$4,800.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : NAZ

Date : 21/4/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees		--		
4. LTA Search Fee / GEARS	\$26.75 / \$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

8AS-KIV

LKX -


SLZ9719Y

CLS

VEHICLE NO.: **SHA1539G**

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- The following:
- + After survey
- + If damaged part(s) during resurvey
- + Parts price subject to confirmation
- + Find parts based on a "Without Prejudice" basis
- + No deduction on part(s) is allowed
- Surveyed part(s) must be resurveyed and
is subject to approval from Insurance Company

Acknowledges: 

Signature: _____

Date: _____