COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 06.04.2023

INSURANCE: INCOME

MODEL:

BYD New E6

MVA: LIM T S

VEHICLE NO.: SHA7575L

ART NO.	DESCRIP	TION	QTY	U	NIT PRICE		AMOUNT	
	Front Door RH		1			\$	2,702.00	100
	Rear Door RH		1			\$	2,702.00	100
	Rocker Panel Garnish RH		1			s	1,101.20	DEF
	Front Wheel Rim RH / LH	RHE LHAR	2	s	1,364.00	\$	2,728.00	ne / SCR
	Rear Wheel Rim RH / LH	62	2	\$	1,364.00		2,728.00	/ser
	Rear Fender Shield RH		1	Ť	.,	\$	223.50	TN
	*	SUB TOTAL				\$	12,184.70	
		LESS 20%				\$	2,436.94	
	DISCOUNTED TOTAL					\$	9,747.76	
		D/						
	Front Wheel Tyre RH / LH		2	\$	316.00	_		NETT 42.
	Rear Wheel Tyre RH / LH	70%	2	\$	316.00	\$	-632.00	NETT 442
	Front Door ComfortDelgro	RH	1			\$	100.00	/NE.
	Rear Door Electric 100% F		1			\$	100.00	-NEC
	Rear Fender Sticker RH (\	White)	1			\$	50.00	INTEC
	Rear Bumper Sticker RH ((White)	1			\$	50.00	-NEC
							200.00	
		S/NETT LESS 10%				\$ \$	300.00 30.00	
		S/NETT TOTAL				\$	270.00	
						·		
		LKRARTSOTOTALS	•			\$	11,281.76	
	Labour Charma	the Repairer of the foll To resurvey before/after s						
	Labour Charge Panel Beating	 To display damaged part(s Parts prices are subject to 					4 000 00	-800
	Spray Painting	Third party survey is on a		e" basi	is	\$ \$	1,000.00 2,500.00	1 1 00
	Tuff Kote	No illegal nonfication s) is				\$	200.00	50
	Check Wirings	 Supplementary item(s) mu is subject to final approva 	si de resurveyed from i <mark>nsura</mark> nce (and ompa	ny	\$	100.00	30
	Transfer of Doors	Acknowledged by Repairer				\$	300.00	240
	Wheel Alignment	Signature:				\$	150.00	XNN
	Towing Fee - King Dolly ⊬	Date:						
		TOTAL LABOUR				\$	4,250.00	
	ESTIMATE TOTAL					\$	15,531.76	
	ALL PARTS PRICE TO	BE CONFRIMED					The state of the s	

vehicle is surveyed by a motor Surveyor appointed by the insurance company

SHIPS 1645

SHIPS 1645

THE SDAYS

CHECK ITEM PHOTOS / BEFORE PAINT PHOTOS