



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD	Ref: NS/INC23003602/Nnp3m4
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557	Date: 04-05-2023
	Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBT 3010Y	Veh. Inspected	SHA 9571J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1216403-002	Excess (\$)	0.00
Assign From		Assign Date	05/04/2023

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ G2	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU141073	Colour	YELLOW
Odometer	297887	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	TRIANGLE	4 mm
L/H Front Tyre	195/65 R15	TRIANGLE	4 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/03/2023	Inspection Date	05/04/2023
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------