

MOTOR SURVEY ASSIGNMENT

Date	10/04/2023	Our Ref No.	D23001158MFQC
Accident Date	03-04-2023	Claim Type	Own Damage
Insured Vehicle	QX1052R	Third Party Vehicle	
Survey Location	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03- 09/10/06 SIN MING AUTOCARE (S) 575721	Contact Person	VENUS LEE
Contact No.	97921329	Fax No.	0

Survey Type Revert for instructions

Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD
Contact Person	Fax No. 68416315
Contact Number	62563561

EXCESS APPLICATION FOR OWN DAMAGE CLAIM ADDITIONAL \$500.00 FOR INSURED VEHICLE INSTALLED WITH CNG TANKER

Basic	Y/I Driver	Total
\$1,000	\$0	\$1,000

Encl. Accident Reports & Estimate \$8379.40

Cc : Workshop LIM TAN MOTOR PTE LTD

Attention VENUS LEE

Officer Incharge VICALPEH

IMPORTANT NOTE

Kindly submit the survey report by **email only** to surveyor@msfirstcapital.com.sg within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.