

24/10 2019 THU 11:09 FAX

001/008

MSME19140977 / SME Motor Pm Ltd - Kaki Bukit
ENTRY DATE & TIME: 23/10/2019 17:34
SUBMITTED BY: Chee Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/10/2019 17:34
Date Of Accident 22/10/2019 18:10
Exact Location Of Accident KAKI BUKIT AVE 2
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SDZ3099L
Insured/Policyholder
Name Of Registered Owner LIM HONG
NRIC No S1683798I
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-91448892
Alternative Phone No OFFICE-91448892
Vehicle Particulars
Manufacturer TOYOTA
Model AXIO
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number S108132453
Cover Note Number
Driver
Name of Driver LIM HONG
NRIC No S1683798I
Date Of Birth 15/12/1965
Occupation INDOOR
Date Of Driving Pass 09/12/1994
Driving Experience 24 YEARS AND 10 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91448892
Fax Number
Contact Number OFFICE-91448892
Email Address NOEMAIL

24/10 2019 THU 11:09 FAX

002/008

Address BLK 134 PASIR RIS ST 11 #05-255
 Postcode S10134
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 22/10/2019 AT ABOUT 6.08PM, I WAS DRIVING ALONG KAKI BUKIT ROAD 1 ON THE RIGHT LANE. WHEN I WAS COMING TO A STOP, CAR B WHICH WAS TURNING INTO KAKI BUKIT ROAD 1 FROM KAKI BUKIT AVE 2 CAME INTO MY LANE AND HIT THE FRONT RIGHT PORTION OF MY CAR A.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA1949J
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver HUANG MING WEI
 NRIC/Passport Number S8836543Z
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

24/10 2019 THU 11:09 FAX

003/008

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/10/19, 3:50pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 23/10/19, 3:50pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


GIANM Sketch (Nameless).V1

BLUWEL

24/10 2019 THU 11:10 FAX

004/008

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/10/19 at about 6.08pm, I was driving along Kaki Bukit Road 1 on the right lane. When I was coming to a stop, Car B which was turning into Kaki Bukit Road 1 from Kaki Bukit Ave 2, came into my lane and hit the front right portion of my car (A).

Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 23/10/19 3:30 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 23/10/19 3:30 pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

GIAPWS SketchPlanForm_V3

2

24/10 2019 THU 11:10 FAX

2005/008

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191023/2008

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852899

1 of 4
Report No. T/20191023/2009

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/10/2019 01:10		Vide Report No.:		Station Diary No.: 10	
Informant's Particulars					
Name of Informant: LIM HONG		Address: APT BLK 134 PASIR RIS STREET 11 #05-255 SINGAPORE 510134			
ID Type / ID No.: NRIC NO / S16837981		Contact No.:		Mobile: 91448892	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Female	Age: 53	Date of Birth: 15/12/1965	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: HR MANAGER		Driving Licence Information: Class: 3		Date of Expiry:	

General information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/10/2019 18:10	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 KAKI BUKIT ROAD 1 KAKI BUKIT AVENUE 2 KAKI BUKIT ROAD 1 Junction of KAKI BUKIT AVENUE 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: No

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SDZ3099L	Car	TOYOTA	COROLLA AXIO 1.5X A	White	Seriously Damaged	0
SLA1948J	Car	TOYOTA	WISH 1.8 CVT	Grey	Slightly Damaged	0

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date	
SDZ3099L	NTUC Income Insurance Co-Operative Limited	5108132453	15/03/2019	25/03/2020	

24/10 2019 THU 11:10 FAX

006/008

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191023/2009

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

2 of 4

Report No. T/20191023/2009

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LIM HONG	ID No.	S16837981
Related Vehicle	SDZ3099L (Car)	Contact No.	91448692
Hospital/Clinic	PARKWAY EAST HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	22/10/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	HUANG MING WEI	ID No.	S86365432
Related Vehicle	SLA1949J (Car)	Contact No.	97115157
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/10/2019 at about 6.10pm, I (SDZ3098L) was stopped behind the stop line of the traffic light junction of Kaki Bukit Road 1 and Kaki Bukit Ave 2. I am on the second lane from the left which only can turn right. While waiting for the traffic light to turn green, 1 vehicle (SLA1949J) make a right turn from Kaki Bukit Ave 2 turning into Kaki Bukit Road 1 and he went into my lane. I was unable to react thus his vehicle hit my vehicle head on.

After the driver of SLA1949J had hit me, he parked at the side of the road. I wanted to moved my vehicle however I found out that I am unable to move my vehicle. I then stepped out of my vehicle and make a checked on my vehicle. After I make a checked on my vehicle and I then checked on the other driver if he need any medical assistance however he informed that it is not necessary. The other driver asked me the same question as I felt vomiting after I came out of my vehicle and I told him that I will seek my own medical assistance afterwards.

My vehicle suffered dented on the right front portion and right front wheel came off from the vehicle.

We then exchanged particulars and I called my workshop to request for towing service. After I called my workshop, the other driver left the incident location. Subsequently, the towing vehicle came and towed away my vehicle. I then left the incident location and went to seek my medical assistance at Parkway East Hospital. Doctor issued me with 3 days MC from 23/10/2019 to 25/10/2019 and I felt pain on my lower back.

24/10 2019 THU 11:11 FAX

007/008

Sketch Plan #5 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20191023/2009

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852888

3 of 4
Report No. T/20191023/2009

CONTINUATION OF REPORT

I wish to state that I have in car camera pointing front and rear. I have the footage downloaded onto my phone and I am unsure if there is any CCTV around the vicinity.

24/10 2019 THU 11:11 FAX

008/008

Sketch Plan #6 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20191023/2008

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

4 of 4

Report No. T/20191023/2008

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G/ Sgt 2 JOHNNY TAN KOK JOO
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / SSI 2 JUBENAH BINTE AHMAD Contact No: 519457
Authentication Stamp NP108

Signature Of Informant:
Date/Time: 23/10/2019 01:10
Classification Of Case:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2019 10:08
Date Of Accident	22/10/2019 18:00
Exact Location Of Accident	KAKI BUKIT AVE 2 JUNCTION OF KAKI BUKIT RD 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA1949J
Insured/Policyholder	
Name Of Registered Owner	HUANG MING WEI (FANG MINGWEI)
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100747434-01
Cover Note Number	

Driver

Name of Driver	HUANG MING WEI (FANG MINGWEI)
NRIC No	S8636543Z
Address	BLK 217C SUMANG WALK #12-222

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

ON THE 22/10/2019 @ 1800HRS, I WAS TRAVELLING ALONG KAKI BUKIT AVE 2 TURNING RIGHT INTO KAKI BUKIT RD ONE. WHEN I WAS NEGOTIATE THE TURN, I MISJUDGE AND COLLISION INTO VEHICLE B.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDZ3099L
Vehicle Make/Model/Colour	
Name of Driver	
Insurance Company Name	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 22/10/2019 @ ord 1800hrs I was travelling along Kaki Bukit Ave 2 turning right into Kaki Bukit Rd One. When I was negotiate the turn, I misjudge and collided into vehicle B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport
/Company Cert No.: S16837981

Owner ID Type: Singapore NRIC

Owner Name: LIM HONG

Registered Address: APT BLK 134 PASIR RIS STREET 11 #05-255 SINGAPORE 510134

Mailing Address: -

Birth Date: 15 Dec 1965

Vehicle Particulars

Vehicle No.: SDZ3099L

Previous Vehicle No.: -

Effective Date of Ownership: 13 Mar 2018

Original Regn Date: 26 Mar 2008

Registration Date: 26 Mar 2008

Year of Manufacture: 2008

Vehicle Type: Private Hire (Chauffeur) Motor Car

Vehicle Scheme: -

Vehicle Attachment 1: No Attachment

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Make: TOYOTA

Vehicle Model: COROLLA AXIO 1.5X A

Primary Colour: White

Secondary Colour: -

Passenger Capacity: 4

Chassis No.: NZE1416068610

Engine No.: 1NZC912931

Engine Capacity /Power Rating: 1496 cc /-

Maximum Power Output: 81.0 kW (108 bhp)

Propellant: Petrol

Max Unladen Weight:	1130 kg
Maximum Laden Weight:	1405 kg
Open Market Value:	\$13,105.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
Minimum PARF Benefit:	-
No. of Transfers:	1
IU Label No.:	1027700318
COE No.:	2008040101003118G
COE Expiry Date:	25 Mar 2028
COE Category:	A - Car (1600cc & below)
COE Registration Category:	A - Car (1600cc & below)
Quota Premium (QP) / Prevailing Quota Premium:	\$15,389.00 / -
PQP Paid:	\$39,274.00
QP (Regn Cat):	\$15,389.00
OPC Cash Rebate Eligibility:	No
QP during COE Bidding Exercise:	\$15,389.00
Additional Registration Fee Rate:	100.00 %
Actual ARF Paid:	\$13,105.00
Vehicle Lifespan Expiry Date:	No Lifespan
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-
Message:	To renew the COE, the Prevailing Quota Premium payable is that of Category A. This is a public service vehicle.



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6655 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 19024-10/MY / 2019
Date of Report : 7 Nov 2019

Lim Hong
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 22 Oct 2019

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated **24 Oct 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SDZ 3099 L**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SDZ 3099 L	Engine No	: 1NZC912931
Model	: Toyota Axio	Mileage	: 431583
Year / Capacity	: 2008/1496	Colour	: White
Chassis No	: NZE1416068610		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S	: 195/60 R15	Falken	4.00 mm	Sport
REAR O/S	: 195/60 R15	Falken	4.00 mm	Sport
FRONT N/S	: 195/60 R15	Falken	4.00 mm	Sport
REAR N/S	: 195/60 R15	Falken	4.00 mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay 5 Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front o/s portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 8 working days to complete.
5. Enclosed number of photograph : 161 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SDZ 3099 L
Report No: TP/ 19024-10/MY / 2019

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Bonnet	Repair	\$ 628.94	\$
1	Bonnet lock	Damage	\$ 118.50	\$ 118.50
2	Front headlamps	Damage	\$ 1330.40	\$ 1330.40
1	Front grille	Damage	\$ 335.60	\$ 335.60
1	Front grille logo	Necessary	\$ 48.50	\$ 48.50
1	Front bumper	Damage	\$ 1251.35	\$ 1251.35
1	Front bumper fog lamp cover	Damage	\$ 28.50	\$ 28.50
1	Front bumper inner sponge	Damage	\$ 120.50	\$ 120.50
1	Front bumper reinforcement	Damage	\$ 355.90	\$ 355.90
2	Front bumper side retainers	Necessary	\$ 97.00	\$ 97.00
1	Front fender	Damage	\$ 706.80	\$ 706.80
1	Front fender inner panel	Repair	\$ 489.60	\$
1	Front fender inner shield	Damage	\$ 189.50	\$ 189.50
1	Front fender inner shield clip (1 set)	Necessary	\$ 34.00	\$ 34.00
1	Front support panel	Repair	\$ 855.96	\$
1	Front brace panel	Damage	\$ 101.50	\$ 101.50
1	Air con condenser	Intact	\$ 1361.83	\$
1	Radiator	Damage	\$ 1626.28	\$ 1626.28
1	Washer tank	Damage	\$ 121.45	\$ 121.45
1	Front wheel bearing	Necessary	\$ 122.50	\$ 122.50
1	Front wheel hub	Damage	\$ 185.00	\$ 185.00
1	Front shock absorber	Damage	\$ 423.50	\$ 423.50
1	Front knuckle arm	Damage	\$ 465.90	\$ 465.90
1	Front lower arm	Damage	\$ 435.80	\$ 435.80
1	Front lower arm ball joint	Damage	\$ 108.50	\$ 108.50
1	Front centre cross member	Damage	\$ 426.59	\$ 426.59
1	Power steering tie rod end	Damage	\$ 86.15	\$ 86.15
1	Power steering rack	Damage	\$ 1899.95	\$ 1899.95
1	Power steering rack cross member	Damage	\$ 856.50	\$ 856.50
1	Front stabilizer bar	Damage	\$ 435.90	\$ 435.90
1	Front stabilizer bar link	Damage	\$ 171.05	\$ 171.05
1	Front o/s drive shaft	Damage	\$ 1687.15	\$ 1687.15
1	Engine front mounting	Damage	\$ 241.05	\$ 241.05
1	Engine rear mounting	Damage	\$ 201.65	\$ 201.65
1	Front door	Repair	\$ 1150.80	\$
			\$ 18700.10	\$ 14212.97
Discount 25.0%			\$ 4675.03	\$ 3553.24
			\$ 14025.07	\$ 10659.73
List Items Sub Total			\$ 14025.07	\$ 10659.73

Vehicle No: **SDZ 3099 L**
 Report No: **TP/ 19024-10/MY / 2019**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
List Items Total c/f			\$ 14025.07	\$ 10659.73
<u>Special Nett Items</u>				
1	Front tyre (Depreciation)	Damage	\$ 320.00	\$ 128.00
1	Front sport rim	Damage	\$ 450.00	\$ 450.00
			<u>\$ 770.00</u>	<u>\$ 578.00</u>

Spare Parts Total \$ 14795.07 \$ 11237.73

Vehicle No: SDZ 3099 L
Report No: TP/ 19024-10/MY / 2019


LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 14795.07	\$ 11237.73
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 60.00	\$ 40.00
2	To remove and refit front undercarriage.	\$ 650.00	\$ 400.00
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 180.00	\$ 120.00
4	To remove and refit air-con system, refill gas and test for leakages.	\$ 160.00	\$ 120.00
5	To remove and refit radiator system.	\$ 150.00	\$ 60.00
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1500.00	\$ 880.00
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1500.00	\$ 1100.00
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 200.00	\$ 120.00
Total		<u>\$ 19195.07</u>	<u>\$ 14077.73</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:



\$ 11300.00


SDLS: ELEVEN THOUSAND THREE HUNDRED ONLY





Qualified Appraiser









































































































































BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28

(Unit C) #01-51/53/55 Singapore 417883

Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088

Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg

Co. Reg. No.: 200704951N

GST Reg. No.: 200704951N

Vehicle No : SDZ 3099 L Date : 7-Nov-19
Make/Model : Toyota Axio
Name : Lim Hong
Address : c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

QTY	ITEM	AMT (\$S)
-----	------	-----------

Lump sum repair costs	\$	11,300.00
GST 7 %	\$	791.00
Grand-total	\$	12,091.00

Dollars : Twelve Thousand And Ninety One Only