Surveyor:

REF: CS1/LAW23003674/Uvy3

Special Instruction:
LS : $ 11300 / 8 DAYS

ASSIGNMENT (Office)

From (Person): CORENE CHONG of CROSSBORDERS LLC Date/Time: 10/04/2023

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant: _____

Surveyor: _____

Workshop: BLUWEL AUTOMOTIVE SERVICE PL

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SDZ 3099L Insured: SLA 1949J

at Workshop m/s BLUWEL AUTOMOTIVE SERVICE PL Tel: _____

of BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883

Policy No: TWK1604.21 Claim No: AJ.tk.6919.2019.BW-PD+PI

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 22/10/2019

(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle **IN / OUT**

Date/Time: _____ **Confirmed with** _____ **Final Fig** _____, ___days (Red $____/___%; Original 7 days)

Date/Time: 4/5/23 **Submit Final Fig** LS $8400, 8 days (Red $ 2900 / 25 %; Original 8 days)

Date/Time	Action/Instruction
	Note: mv:$41,500 LTA rebate as at 22.10.2019 $33055 nv:8445.00

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

50/50

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____