

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 1	9-96071	198-R	
		Affiliated to Federation Internation	nale Des Experts En A	utomo	bile	
	AUTO & GENERA	L INSURANCE (S) PL	R	Ref:	CS/AGI23003675/Uny3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	ate:	18/04/2023	
			C	ode:	AGI	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLU 1800Z	Veh. Inspected		VGM 227	
	Policy No.	P10823171R00	Coverage (\$)		0.00	
	Claim No.	C10021493 /CD	Excess (\$)		0.00	
	Assign From	FRAULEINE KHOO	Assign Date		10/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA Y15ZR	c.c		150	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	PMYUG0520L0176545	Colour		RED	
	Odometer	-	Steering		AFFECTED	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	70-90-17	MAXXIS		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80-90-17	MAXXIS		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/04/2023	Inspection Date		11/04/2023	
	Survey held at	vey held at EROFIA MOTOR TRADING PTE LTD				
		1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	DJIN ACCORDANC	Estimate Days of Repair				
	Latiniate Daya Of Nepali					

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: