

ASS. REC. BY: Taufik

REF:

CS/ TM 23003678/Tvy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **GBH 1552B**Policy No. **MZC00344**Claims No. **M2302263**


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

GMTSVeh No: SMD4758EYr Regn: 2019, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Priusc.c. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 43733

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDKB3F430308794

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: (NI) / S/Rim / STD A/Rim orTyre Size: F: P15/65R15R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Worlbyke

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 4/4/2023D.O.I. 11/4/23Survey held at Garage by

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Mirror.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/4/23 Final fig \$1464.99 confirmed by email (red 435.01, 29%)

Date/Time, File Pass to?

☐

: Preli. Report

1) _____

☐

: Final Report

Date/Time, File Return to?

2) 14/4/23-typistRep. Format: MerimenLump Sum / I.B.R. (1464.99)Days Of Repair: 1Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

CP/P)

LKK -

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/04/2023
Vehicle Reg. No.:	SHD4758E	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	05/12/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2F76912	Chassis No:	JTDKB3FU303089947
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	2		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,149.00
Miscellaneous Items	11.00
Labour	740.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,900.00
+ GST 8.00% (S\$)	152.00
Nett Amount (S\$)	2,052.00

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

10/4 @ 13:59 hrs

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Apr 2023)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD4758E/10/04/2023 13:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Lim Tien Siong

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*WING MIRROR LH	25.00	0.00	<i>Che</i> *1,390.10 FL
2	1		*WING MIRROR OUTER COVER LH	25.00	0.00	<i>Mis</i> *141.90 FL
Sub Total (S\$)						1,532.00
- List Item Discount on L Items (S\$)						383.00
Total Parts (S\$)						1,149.00

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD4758E/10/04/2023 13:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	175 400.00
2	SPRAY PAINTING	New	100 300.00
3	CHECK WIRINGS	New	30 40.00
Gross Labour Cost (S\$)			740.00

ComfortDelGro Engineering Pte Ltd/SHD4758E/10/04/2023 13:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Hin 97495749
WP' 11/4/23 24pm
P/B Remy before paint
01 day
for 8pm C (Mentor)

LKK Auto Consultants must notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date/Time: 10.04.2023 12:26

Page : 1

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5892457

JC NO305550875

Customer: COMFORT TRANSPORTATION PTE LTD
Vehicle No: 7010045
Address: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
Phone: 65508755 (O)
(R)
(P)

REGN NO: SHD4758E	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL: PRIUS HYBRID(G4A10)	DATE/TIME IN 04.2023 10:45
YR OF MANU: 05.12.2019	TARGET DATE
CHASSIS CODE: JTDKB3FU303089947	COMPLETION DATE/TIME:


UNIT CARD NO.

JOB DESCRIPTION

cident Date: 04.04.2023
TURE: 3P 04.04.2023

NO LABOR CODE
0010 PB

DESCRIPTION
PANEL BEATING-SHD4758E-TP



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vehicle No.: SHD4758E

LIMITS

Vehicle No.: SHD4758E

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard