



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS XIAO

Ref: CS/INC23003709/Awy3m4

Date: 24/05/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | SLQ 6033J | Veh. Inspected | SLG 7264E |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1217702-001 | Excess (\$) | 0.00 |
| Assign From | JESS TOH | Assign Date | 11/04/2023 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|------------|
| Make & Model | MAZDA 3 | c.c | 1496 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | JM6BM42A8G0344808 | Colour | WHITE |
| Odometer | 240731 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-----------|--------|---------|
| R/H Front Tyre | 205/60R16 | KAPSEN | 6 mm |
| L/H Front Tyre | 205/60R16 | KAPSEN | 6 mm |
| R/H Rear Tyre | 205/60R16 | KAPSEN | 6 mm |
| L/H Rear Tyre | 205/60R16 | KAPSEN | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|---------------------|-------------------------|
| Accident Date | 06/04/2023 | Inspect Date / Time | 11/04/2023 (01:00 PM) |
| Survey held at | HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days