

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI23003712/Kvy3m4	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	e: 19/04/2023	
			Cod	le: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLQ 6200T	Veh. Inspected	SBQ 8860T	
	Policy No.	P10427341R02	Coverage (\$)	0.00	
	Claim No.	C10021616/CH	Excess (\$)	0.00	
	Assign From	FRAULEINE KHOO	Assign Date	11/04/2023	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES E200 (A)	c.c	1991	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	WDD2130422A414806	Colour	METALLIC DARK GREEN	
	Odometer	45884 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/45 R18	PIRELLI	7 mm	
	L/H Front Tyre	245/45 R18	PIRELLI	7 mm	
	R/H Rear Tyre	245/45 R18	PIRELLI	7 mm	
	L/H Rear Tyre	245/45 R18	PIRELLI	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/04/2023	Inspection Date	12/04/2023	
	Survey held at	TSR AUTOMOTIVE PTE LTD	•		
		160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: