



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23003716/Uvy3q2 Date: 02/05/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKX 5786B	Veh. Inspected	GBH 349D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10021624 /JL	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	11/04/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	FIAT DOBLO CARGO MAXI	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZFA26300006H37578	Colour	WHITE	
Odometer	164722 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	LASSA	6 mm	
L/H Front Tyre	195/60 R16	LASSA	6 mm	
R/H Rear Tyre	195/60 R16	LASSA	6 mm	
L/H Rear Tyre	195/60 R16	LASSA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/04/2023	Inspection Date	11/04/2023	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	