

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	20/04/2023 13:48 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	09/04/2023 12:17 (SGT)
Exact Location of Accident	Near 9V34+9W Singapore
Additional Location Information	SLIP ROAD OF ANG MO KIO AVE 1 TOWARD CTE (CITY)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM4786C
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WANG ZHIJA
NRIC No	S8802949F
Email Address	W.JHIJIA88@GMAIL.COM
Mobile Phone No	(Phone) +65-96561899
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	COROLLA ALTIS
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2003805806-01

DRIVER

Name of Driver	WANG ZHIJA
NRIC No	S8802949F
Date Of Birth	29/01/1988
Occupation	Indoor

Date Of Driving Pass	22/10/2010
Driving experience	12 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96561899
Alt. Phone Number	-
Email Address	W.JHIJIA88@GMAIL.COM
Address	BLK 310B ANG MO KIO AVE 1 #08-381
Address complement	-
Postcode	562310
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	No Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	NG WEI MIN ANGELA
Gender	Female

PASSENGER 2

Name	WANG KAI LER CAELED
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMZ5558J
Vehicle Manufacturer	Tesla
Vehicle Model	MODEL Y
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

VEH A: SJM4786C
VEH B: SMZ558J
VEH C: AIL---

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

12:38
20/4/2023
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Accord Auto Services
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

Hand-drawn sketch plan on a grid background. It shows a road layout with a "Road Work" area marked with a cross-hatched rectangle. Below this, there are two circular diagrams, each with a cross inside, possibly representing vehicles or specific locations. At the bottom, there is handwritten text: "Stop Rd of Ang Mo Kio Ave 1" and "twd (TE City)".

Describe Circumstance of the Accident		
DATE OF ACCIDENT: 9/4/23		TIME OF ACCIDENT: 12/7hrs
VEH A: SM4786	VEH B: SMZ5552J	VEH C: NIL
<p>I was turning into CTE (southbound) from Ang Mo Kio Ave 1. There was road worker on the left 2 lanes along the slip road into CTE. I was driving behind a white Tesla Model Y. The Model Y suddenly jammed brake, and I followed thereafter. I did I did not feel any 'bump' or collision sound, neither did my passengers.</p> <p>Shortly after the Model Y drove continued driving without stopping or signaling to indicate that collision accident have occurred. While the Model Y was driving off, I noticed there is no visible marks or damage on the its rear end.</p> <p>As I was heading towards my destination, I drove past the Model Y once more, and saw the driver was just ^{and saw the driver was just} proceeding as if no collision has occurred ^{as if no collision has occurred}. I verified that there's no damage to my vehicle upon reaching my destination.</p> <p>Unfortunately, my ^{vehicle} recordings was ^{were} overwritten as it was more than 7 days. There's ^{There's} no photograph of the 'collision' as well. I only knew about ^{about} claim against my motor insurance upon receiving ^{receiving} a letter from LK Auto Consultants Pte Ltd on 19 April 2023.</p>		

Declaration

I/We declare the foregoing particulars are true in every respect.

12:38
20/4/2023

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



 Witnessed by Reporting Centre Personnel
 (Name as in NRIC/ID card)




















Add a Caption

Wednesday • 19 Apr 2023 • 15:44

[Adjust](#)

 IMG_1444

Apple iPhone 11

HEIF

Wide Camera — 26 mm $f1.8$

12 MP • 4032 × 3024 • 1.5 MB

ISO 640

26 mm

0 ev

$f1.8$

1/35 s

[Add a location...](#)

[Show in All Photos](#)





