

ASS. REC. BY: Tajp

REF:

IN C
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	2

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH197780K Yr Regn: 2020, Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 325639 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKR3F4153091390

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westfalo

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 11/4/23Survey held at Garage byay

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.A. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7780K
MAKE TOYOTA
MODEL PRIUS

DATE: 11.04.23

MVA JUMANI

DOA: 10.04.23

(CLISUM)

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			de ✓ \$503.04
1	REAR BUMPER CENTRE MLDG			de ✓ \$654.96
1	REAR BUMPER BEAM			? \$318.80
1	REAR FLOOR UNDER COVER			? \$220.50
10	REAR BUMPER CLIPS			net ✓ \$22.00
1	BOOTLID EMBLEM – PRIUS			net ✓ \$62.14
1	BOOTLID EMBLEM – HYBRID			net ✓ \$62.14
1	BOOTLID EMBLEM – STAR			net ✓ \$81.43
1	REAR BUMPER TOW COVER			de ✓ \$82.70
1	REFLECTOR RH			? \$55.00
1				
	SUB TOTAL			\$2,062.71
	DIS 25%			\$515.67
	DISCOUNTED TOTAL			\$1,547.04
	BOOTLID COMFORT LOGO			net ✓ \$30.00 NET
	BOOTLID COMFORT TEL.NOS LOGO			net ✓ \$30.00 NET
	BOOTLID APPS LOGO			net ✓ \$40.00 NET
	REVERSE SENSOR			net ✓ \$180.00 NET
				\$280.00
	Labour Charge			
	PANEL BEATING –			\$25 \$800.00
	SPRAY PAINT			\$50 \$600.00
	REMOVE/REFIX REVERSE SENSOR			30 \$50.00
	CHECK WIRING			x \$50.00
	TUFF KOTE			x \$50.00
	Tanjin 97445749			
	wpt 11/4/23 @ 320pm			
	2/5 Resurvey after repair			
	Tanjin Chhankar			
	2-3 days			
	TOTAL LABOUR			\$1,550.00
	ESTIMATE TOTAL			\$3,377.04
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5892657

JC NO305550947

OMER

REGN NO:

SHA7780K

MILEAGE

S COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO

ESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

(R)

(P)

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4A11.04.2023 12:15

DATE/TIME IN

YR OF MANU

04.08.2020

TARGET DATE

CHASSIS CODE

JTDKB3FU103091390

COMPLETION DATE/TIME:

JUNT CARD NO.

JOB DESCRIPTION


Accident Date: 10.04.2023

ATURE: 3P.10.04.23

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Io.: SHA7780K

JU INCOME

Vehicle No.:

SHA7780K

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard