

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 11.04.23

D.O.A 11.04.23

MODEL: Hyundai Ioniq

INSURANCE: **INCOME**

(Lisum)

VEHICLE NO.: SHC3413L

MVA: **JUMANI**

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	FRT BUMPER	10		\$ 481.10
	FRT BUMPER CLIPS			\$ 22.00
	FRT FENDER SHEILD LH			\$ 164.70
	FRT BUMPER SIDE BRACKET LH			\$ 35.00
	HEADLAMP ASSY LH			\$ 2,110.30
	FRT FOG LAMP GRILLE LH			\$ 93.45
	FRT FOG LAMP LH			\$ 642.50
	FRT BUMPER MOULDING CENTRE			\$ 368.50
	SUB TOTAL			\$ 3,917.55
	LESS 20%			\$ 783.51
	DISCOUNTED TOTAL			\$ 3,134.04
	SUB - TOTAL			
	<u>Labour Charge</u>			
	PANEL BEATING			\$ 400.00
	SPRAY PAINT			\$ 300.00
	WIRING CHARGE			\$ 50.00
	TUFF KOTE			\$ 50.00
	TOTAL LABOUR			\$ 800.00
	ESTIMATE TOTAL			\$ 3,934.04

*for
net
for
de
net
net
?*

NET
NET
NET

*350
250
30
7*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tanglin 97475749
WP 11/4/23 04pm
LIS rising after repair
2 days
Tanglin@lkkauto.com*

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Workshops

Date/Time: 11.04.2023 13:33

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5892646


JC NO305550943

OMER	REGN NO: SHC3413L	MILEAGE
S COMFORT TRANSPORTATION PTE LTD 7010045	MAKE HYUNDAI	FUEL E.....1/2.....F
OMER NO 383 SIN MING DRIVE ESS Singapore SINGAPORE 575717 65508755 (O)	MODEL IONIQ(G2) 11.04.2023 11:50	DATE/TIME IN
(R) (P)	YR OF MANU 12.07.2018	TARGET DATE
DUNT CARD NO.	CHASSIS CODE KMHC851CVJU103547	COMPLETION DATE/TIME:

Accident Date: 11.04.2023
NATURE: 3P.11.04.23/C

JOB DESCRIPTION

NO LABOR CODE DESCRIPTION



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Adgement Slip

Exit Pass

Vehicle No.: SHC3413L JU INCOME

Vehicle No.: SHC3413L

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard