

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23003765/Tny3m4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date: Code:	09-05-2023 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLJ 4293A	Veh. Ir	spected	SHD 8572Y	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1221283-001	Exces	,	0.00	
	Assign From		Assign	Date	11/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU093741	Coloui	•	YELLOW	
	Odometer	730275	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60R16	WEST		6 mm	
	L/H Front Tyre	205/60R16	WEST		6 mm	
	R/H Rear Tyre	205/60R16	WEST	_AKE	6 mm	
	L/H Rear Tyre	205/60R16	WEST	_AKE	6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	11/04/2023	Inspec	tion Date	11/04/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					