

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





| AUTOMOBILE INSPECTION REPORT                        |   |            |        |                     |            |  |
|---|---|------------|--------|---------------------|------------|--|
| INCOME INSURANCE LTD                                |   |            | Ref:   | NS/INC23003767/Tvy3 |            |  |
| 75 BRAS BASAH ROAD<br>INCOME CENTRESINGAPORE 189557 |   |            | Date:  | 12-04-2023<br>INC4  |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM          |   |            |        |                     |            |  |
| Insured   | Veh.  | SMC 963B   |        | spected             | SHC 8339K  |  |
| Policy No.  |   |            | Covera | age (\$)            | 0.00       |  |
| Claim N   | ο.  |            | Exces  | s (\$)              | 0.00       |  |
| Assign  | From  |            | Assign | n Date              | 11/04/2023 |  |
| 2. Vehicle Particulars & Condition                  |   |            |        |                     |            |  |
| Make &  | Model   |            | c.c    |                     | 0          |  |
| Engine  | No.   | HIDDEN     | Year o | f Reg.              |            |  |
| Chassis No.   |   |            | Colour |                     |            |  |
| Odomet  | Odometer -  |            |        | Steering            |            |  |
| Brakes  | Brakes  |            |        | Modification        |            |  |
| General   | General   |            |        |                     |            |  |
| 3. Conditions of Tyres                              |   |            |        |                     |            |  |
|   |   | Size       | Make   |                     | Balance    |  |
| R/H Fro   | nt Tyre   |            |        |                     | mm         |  |
| L/H From  | nt Tyre   |            |        |                     | mm         |  |
| R/H Rea   | r Tyre  |            |        |                     | mm         |  |
| L/H Rea   | r Tyre  |            |        |                     | mm         |  |
| 4. Description of Damages                           |   |            |        |                     |            |  |
|   |   |            |        |                     |            |  |
| 5. General Information                              |   |            |        |                     |            |  |
| Acciden   | t Date  | 09/04/2023 | Inspec | tion Date           | 11/04/2023 |  |
| Survey  | Survey held at COMFORTDELGRO ENGINEERING PTE LTD  |            |        |                     |            |  |
|   | 59 LOYANG DRIVE<br>SINGAPORE 508969   |            |        |                     |            |  |
| 5a.   |   |            |        |                     |            |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |            |        |                     |            |  |