

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ 2483Aat Workshop m/s ARCof 48, tott luan rd eos #02-146Insured: CTI

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Clients Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 87K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBJ 2483A Yr Regn: 2019 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna 3.0M c.c. 2982Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 91326 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KDY2318029332

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15CR: 155R13C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 5/5 mmL/Bal. 7 mm L/Bal. 5/5 mmD.O.A. 30/03/23 D.O.I. 25/04/23Survey held at ARCDes. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 73K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS \_\_\_\_\_ SI

Photos

Others

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_ )

☐

: Interview (\$ \_\_\_\_\_ )

☐

: Tech. Invs (\$ \_\_\_\_\_ )

☐

: Weekend (\$ \_\_\_\_\_ )

TOTAL

**Automotive Repair Centre Pte Ltd**  
**#05-18, Singapore 757700, 38**  
**Woodlands Industrial Park E1**  
**757700**

**Insurer Reference:**

**Repairer Reference: 059569**

**Date calculated: 10/04/2023 3:03 PM**

**Full Report**

**Registration: GBJ2483A**

**Printed: 10/04/2023 3:14 PM**

**Summary Information**

---

**Claim**

|                        |                |                   |                                                |
|------------------------|----------------|-------------------|------------------------------------------------|
| Location:              | Singapore (SG) | Work Provider:    | China Taiping Insurance<br>(Singapore) Pte Ltd |
| Printed by:            | RAYMOND TAN    | Currency:         | SGD                                            |
| Claim Reference:       |                | Date of Incident: | 30/03/23                                       |
| Estimated Repair Time: |                | Hire Car Start:   |                                                |
| Actual Repair Days:    |                | Hire Car End:     |                                                |

**Vehicle Details**

---

**Vehicle**

|                     |            |
|---------------------|------------|
| Manufacturer:       | TOYOTA     |
| Model:              | DYNA       |
| Sub Model:          | BASE MODEL |
| Model Sheet Number: | 70 1N 01   |
| Registration:       | GBJ2483A   |

VIN number:

Odometer:

**Model Specs**

PLATFORM

## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:

Date of Inspection:

### Damage Areas

All ☐  
Underbody ☐



## Tyres Condition

| Tyre Brand | Tread (Left Middle),<br>mm | Tread (Left Outer),<br>mm | Tread (Left Inner),<br>mm | Tread (Right Inner),<br>mm | Tread (Right Outer),<br>mm | Tread (Right<br>Middle), mm | Condition |
|------------|----------------------------|---------------------------|---------------------------|----------------------------|----------------------------|-----------------------------|-----------|
|------------|----------------------------|---------------------------|---------------------------|----------------------------|----------------------------|-----------------------------|-----------|

| Spare Tyre Brand | Tread (Spare), mm |
|------------------|-------------------|
|------------------|-------------------|

## Labour

| Code                             | Description                  | Time Base 10 WU/h | Price = 42.00 SGD/h |           |
|----------------------------------|------------------------------|-------------------|---------------------|-----------|
|                                  |                              |                   | WU                  | Price SGD |
| NO NUMBER                        | R + R REAR LOADING LID       |                   | 6.0                 | 25.20     |
| NO NUMBER                        | R + R L/FOLDING GATE SUPPORT |                   | 2.0                 | 8.40      |
| 811011                           | R + R LEFT TAIL LAMP         |                   | 3.0                 | 12.60     |
| NO NUMBER                        | RENEW L/TAILLAMP ATTACHMENT  |                   | 2.0                 | 8.40      |
| 5403                             | PLATFORM FLOOR REPAIR        |                   | 10.0*               | 42.00     |
| <b>Labour Cost</b>               |                              |                   |                     |           |
| <b>Panel / Mechanical Labour</b> |                              | <b>Hrs</b>        | <b>WU</b>           |           |
|                                  |                              | 2.30              | 23.0                | 96.60     |
| <b>Total of Labour</b>           |                              |                   |                     | 96.60     |

## Paint

Paint Work

| Code | Description                         | SYSTEM AZT | Time Basis 10 WU/h |           |
|------|-------------------------------------|------------|--------------------|-----------|
|      |                                     |            | WU                 | Price SGD |
|      | REAR LOADING LID NEW PART PAINTING  |            | 14.0               |           |
|      | PLATFORM FLOOR REPAIR PAINTING <50% |            | 57.0               |           |

## Paint Work

| Code | Description | SYSTEM AZT | Time Basis 10 WU/h | WU | Price SGD |
|------|-------------|------------|--------------------|----|-----------|
|------|-------------|------------|--------------------|----|-----------|

## Paint Material Per Part

| Code | Description                         | Price SGD |
|------|-------------------------------------|-----------|
| 5385 | REAR LOADING LID NEW PART PAINTING  | 30.63     |
| 5403 | PLATFORM FLOOR REPAIR PAINTING <50% | 126.00    |

## Labour Cost - Paint

|                             | Hrs            | WU          | Price SGD     |
|-----------------------------|----------------|-------------|---------------|
| Factor                      | 42.00 SGD/h    |             |               |
| Time Paint                  |                | 71.0        |               |
| Preparation Main Work Metal | 1.70           | 17.0        | 71.40         |
| <b>Total</b>                | <b>10 WU/h</b> | <b>88.0</b> | <b>369.60</b> |

## Material Cost - Paint

|                         | Price SGD     |
|-------------------------|---------------|
| New Part Painting       | 30.63         |
| Repair Painting         | 126.00        |
| Material-constant Metal | 18.10         |
| <b>Total</b>            | <b>174.73</b> |

## Spare Parts

| Code             | Description                    | Part Number   | Part Source | prices as at 2015-06-01/01 | Price SGD       |
|------------------|--------------------------------|---------------|-------------|----------------------------|-----------------|
| 3617             | BADGE MODEL <i>mc</i>          | 75471 25030   | Original    |                            | 35.00           |
| 5419             | L/LOADING LID SUPP <i>?</i>    | 66014 25010   | Original    |                            | 100.00          |
| 5417             | L/REAR PANEL BRAKE <i>?</i>    | 66280 25010   | Original    |                            | 144.00          |
| 3281             | L/R LAMP ASSY <i>ca</i>        | 81560 25100   | Original    |                            | 150.00          |
| 3621             | L/TAILLAMP PANEL <i>repair</i> | 75136 25010   | Original    |                            | 95.00           |
| 3025             | REAR BADGE "TOYOTA" <i>X</i>   | 75995 37020A3 | Original    |                            | 35.00           |
| 5385             | REAR LOADING LID <i>by</i>     | 65700 26010   | Original    |                            | 650.00          |
| f: OEM Parts     | <b>Savings</b>                 |               |             |                            | 0.00            |
| n: Non-OEM Parts | <b>Subtotal</b>                |               |             |                            | 1,209.00        |
| u: Used parts    | <b>Addition(+10.00%)</b>       |               |             |                            | 120.90          |
|                  | <b>Total</b>                   |               |             |                            | <b>1,329.90</b> |

## Extras

| Code | Description                             | Price SGD    |
|------|-----------------------------------------|--------------|
| 1000 | NUMBER PLATE NUMBER PLATE <i>SEA</i>    | 35.00*       |
| 1001 | 70KM/H STICKER 70KM/H STICKER <i>mc</i> | 25.00* 10    |
|      | <b>Total Extras</b>                     | <b>60.00</b> |

## Final Calculation

|                                       | SGD      | SGD             |
|---------------------------------------|----------|-----------------|
| <b>Parts</b>                          |          |                 |
| Addition(+10.00%)                     | 1,209.00 |                 |
| <b>Total Parts</b>                    | 120.90   | <b>1,329.90</b> |
| <b>Labour Time Base 10 WU/h</b>       |          |                 |
| Total 23.0 WU X 42.00 SGD/h           | 96.60    |                 |
| <b>Total of Labour</b>                |          | <b>96.60</b>    |
| <b>Total Of Extras</b>                |          | <b>60.00</b>    |
| <b>Paint Work Time Base 10 WU/h</b>   |          |                 |
| Labour Cost 88.0 WU X 42.00 SGD/h     | 369.60   |                 |
| Material Cost                         | 174.73   |                 |
| <b>Total Paint Including Material</b> |          | <b>544.33</b>   |
| <b>Repair Cost Excludes GST</b>       |          | <b>2,030.83</b> |
| GST (+8.00%)                          |          | <b>162.47</b>   |
| <b>Repair Cost Included GST</b>       |          | <b>2,193.30</b> |

### Comments

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Rasm  
Hp 90010068  
4 days  
48  
25/04/23 @ 15:15  
Reg after repair

## Enquire PARF/COE Rebate for Registered Vehicle

|                               |                         |
|-------------------------------|-------------------------|
| Owner ID Type:                | Company                 |
| Owner ID:                     | 670K                    |
| Vehicle No.:                  | GBJ2483A                |
| Vehicle to be Exported:       | No                      |
| Intended Deregistration Date: | 26 Apr 2023             |
| Vehicle Make:                 | TOYOTA                  |
| Vehicle Model:                | DYNA 3.0 MANUAL         |
| Primary Colour:               | Silver                  |
| Manufacturing Year:           | 2017                    |
| Engine No.:                   | 1KD2708369              |
| Chassis No.:                  | KDY2318029332           |
| Maximum Power Output:         | -                       |
| Open Market Value:            | \$34,468.00             |
| Original Registration Date:   | 01 Mar 2019             |
| First Registration Date:      | 01 Mar 2019             |
| Transfer Count:               | 1                       |
| Actual ARF Paid:              | \$1,724.00              |
| PARF Eligibility:             | No                      |
| PARF Eligibility Expiry Date: | -                       |
| PARF Rebate Amount:           | \$0.00                  |
| COE Expiry Date:              | 28 Feb 2029             |
| COE Category:                 | C - Goods Vehicle & Bus |
| COE Period(Years):            | 10                      |
| PQP Paid:                     | \$22,432.00             |
| COE Rebate Amount:            | \$13,098.00             |
| <b>Total Rebate Amount:</b>   | <b>\$13,098.00</b>      |


The information contained herein is correct as at 26 Apr 2023

OK

# Toyota Dyna 150 3.0M

**\$87,838** Instalment \$1,353/mth

 Shortlist  Loan Calculator



**Overview** Financial Photo Research

|               |                                                                                                          |
|---------------|----------------------------------------------------------------------------------------------------------|
| Depreciation  |  \$15,020 / year        |
| Reg. Date     | 01-Mar-2019<br>(5yrs 10mths 2days COE left)                                                              |
| Lifespan      |  28-Feb-2039          |
| Manufactured  |  2018                 |
| Mileage       | 76,552 km (18.4k / year)                                                                                 |
| Transmission  | Manual                                                                                                   |
| Engine Cap    | 2,982 cc                                                                                                 |
| Curb Weight   |  1,780 kg             |
| Fuel Type     | Diesel                                                                                                   |
| COE           |  \$25,264             |
| OMV           |  \$27,082             |
| ARF           |  \$1,355              |
| Dereg Value   |  \$14,778 as of today |
| No. of Owners |  1                    |

Type of Veh **Truck**