

ASS. REC. BY: TaufikREF: 036/41523003771/Tnps.

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: 169

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: 9110K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: EW 122BYr Regn: 2021 MarchType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avantec.c. 1598Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading 51941

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHLCN41ETNU455430Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S Rim / STD A/Rim orTyre Size: F: 205/55R16R: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / XOKO or

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. \_\_\_\_\_

D.O.I. \_\_\_\_\_

Survey held at KFS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / L&amp;A: \_\_\_\_\_



# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

### PARTICULARS OF CLAIM

|                               |                                     |                       |                   |
|-------------------------------|-------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                     | Ref. No:              |                   |
| Policy No:                    | SP2003090998                        | Date of Loss:         | 07/04/2023        |
| Vehicle Reg. No.:             | EW122B                              | Driveable?            |                   |
| Driver Age/Info:              |                                     | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                  | Third Party Involved? | YES               |
| Insured/Claimant:             | YIO PEIQI(YAO PEIQI)                |                       |                   |
| Make/Model:                   | HYUNDAI AVANTE, 1.6 (A)             | Vehicle Reg. Date:    | 12/03/2021        |
| Vehicle Colour:               | METALLIC BLACK                      | Chassis No:           | KMHLN41ETNU155430 |
| Engine No:                    | G4FMMU261850                        |                       |                   |
| Odometer:                     | 0 KM                                |                       |                   |
| Paint Type:                   |                                     |                       |                   |
| Total Loss?                   | NO                                  |                       |                   |
| Est. Duration of Repair (day) | 5                                   |                       |                   |
| Present Location:             | KAN FOOK SING MOTOR WORKSHOP (DEFU) |                       |                   |

### COST OF CLAIMS

|                              | Amount   |
|------------------------------|----------|
| Parts                        |          |
| Miscellaneous Items          | 2,011.90 |
| Labour                       | 0.00     |
| Paintwork Labour             | 570.00   |
| Towing                       | 550.00   |
|                              | 0.00     |
| Calculated Gross Total (S\$) | 3,131.90 |
| - Excess (S\$)               | 600.00   |
| (S\$)                        | 2,531.90 |
| + GST 8.00% (S\$)            | 202.55   |
| Nett Amount (S\$)            | 2,734.45 |

This claim is handled by: MT TAN

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Apr 2023)

Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/EW122B/11/04/2023 14:22

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

| No. | Qty | Part No. | Particulars                      | %Disc | %Depr | Amount            |
|-----|-----|----------|----------------------------------|-------|-------|-------------------|
| 1   | 1   |          | *FRONT HEADLAMP LH               | 0.00  | 0.00  | *1,200.00 F int ✓ |
| 2   | 1   |          | *FRONT HEADLAMP LOWER BRACKET LH | 0.00  | 0.00  | *26.00 F ?        |
| 3   | 1   |          | *FRONT GRILLE                    | 0.00  | 0.00  | *320.00 F int ✓   |
| 4   | 1   |          | *FRONT BUMPER                    | 0.00  | 0.00  | *240.00 F de ✓    |
| 5   | 1   |          | *FRONT BUMPER SIDE RETAINER LH   | 0.00  | 0.00  | *18.00 F ?        |
| 6   | 10  |          | *FRONT BUMPER CLIP               | 0.00  | 0.00  | *25.00 F neu ✓    |

F=Franchise part.

Sub Total (\$\$) 1,829.00

+ Margin on L,N Items 10.00% (\$\$) 182.90

Total Parts (\$\$) 2,011.90

Kan Fook Sing Motor Workshop/EW122B/11/04/2023 14:22. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                                                                      | Lab.Type | Amount     |
|-------------------------|----------------------------------------------------------------------------------|----------|------------|
| <u>Paintwork Labour</u> |                                                                                  |          |            |
| 1                       | SPRAYPAINTING CHARGES                                                            | New      | 250 550.00 |
| <u>Labour Items</u>     |                                                                                  |          |            |
| 2                       | TO CHECK WIRING SYSTEM                                                           | New      | 30 50.00   |
| 3                       | TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS | New      | 250 520.00 |
| Gross Labour Cost (S\$) |                                                                                  |          | 1,120.00   |

Kan Fook Sing Motor Workshop/EW122B/11/04/2023 14:22. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97795749 26/4/23

p/p Resurvey before paint

2-3 days

Ex: fba

Revert

No f furtherise.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: