



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI23003774/Uqy3q2 Date: 24/04/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLV 282U	Veh. Inspected	SJG 9576R
Policy No.	P10802283R00	Coverage (\$)	0.00
Claim No.	C10021628/JY	Excess (\$)	0.00
Assign From	DON BONG	Assign Date	12/04/2023
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT (A)	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	GE61087283	Colour	RED
Odometer	243857 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	FALKEN	6 mm
L/H Front Tyre	195/55 R15	FALKEN	6 mm
R/H Rear Tyre	195/55 R15	FALKEN	6 mm
L/H Rear Tyre	195/55 R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/04/2023	Inspection Date	12/04/2023
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	