

(08/11/13) wof
ASS. REC. BY: [Signature]

REF:

NS/INC23003787/Rqp3

821R

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC20454 Yr Regn: 2019 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i20 1.6 Oct c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 411917 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH C851CVLU189093

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WESTLAK

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 08/04/23 D.O.I. 10/04/23

Survey held at CentFort

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rasul finalised LS \$2500, 5 days. (Red \$3353.36, 57%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 5

1) _____
Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: 1

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : TP

Lump Sum H.B.H. (\$ 2500)

Date/Time: 10.04.2023 12:51

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5892462

JC NO: 305550878


CUSTOMER /MS 7010045 STOMER NO. 383 SIN MING DRIVE DRESS Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO. SHC2045Y	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL TONIQ(G3)	DATE/TIME IN 10.04.2023 08:45
	YR OF MANU 14.11.2019	TARGET DATE
	CHASSIS CODE RMHC551CVLU189093	COMPLETION DATE/TIME:

COUNT CARD NO.

Accident Date: 08.04.2023
NATURE: 3P 08.04.2023

JOB DESCRIPTION

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge ment Slip

Exit Pass

Vehicle No.: SHC2045Y

No.: SHC2045Y

CHIANG

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2045Y

MAKE REG. 14.11.2019

08.04.2023

MODEL IONIQ G2

CHIANG/1NCOME

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER <i>Repair</i>		\$459.40
1	REAR BUMPER SIDE BRACKET LH <i>2?</i>		\$55.80
1	REAR BUMPER REINFORCEMENT <i>?</i>		\$394.80
2	REAR BUMPER REINFORCEMENT LH/RH <i>?</i>		\$276.20
1	REAR BUMPER CENTRE MOULDING <i>see</i>		\$451.25
1	REAR TOW COVER <i>X</i>		\$38.80
10	REAR BUMPER CLIPS <i>see</i>		\$22.00
	SUB TOTAL		\$1,698.25
	20.00%		\$339.65
	DISCOUNTED TOTAL		\$1,358.60
1	REAR NUMBER PLATE W/HOLDER <i>cta</i>		\$55.00
1	REAR BUMPER MAT <i>X</i>		\$50.00
1	REAR REVERSE SENSOR <i>X</i>		\$180.00
			\$261.50
	Labour Charge		
	Panel Beating		350 \$600.00
	Spray Painting Charge		280 \$300.00
	Check Lighting and Wiring		X \$60.00
	Remove/refix Reverse sensor		40? \$80.00
	TOTAL LABOUR		\$1,020.00
	ESTIMATE TOTAL		\$2,640.10
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Passul
Hp 90010068
3 days
4/3
10/04/23 @ 1630
Resurvey after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	821R
Vehicle No.:	SHC2045Y
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Apr 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU406235
Chassis No.:	KMHC851CVLU189093
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,344.00
Original Registration Date:	14 Nov 2019
First Registration Date:	14 Nov 2019
Transfer Count:	0
Actual ARF Paid:	\$12,482.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2027
PARF Rebate Amount:	\$9,361.00
COE Expiry Date:	13 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,933.00
COE Rebate Amount:	\$14,875.00
Total Rebate Amount:	\$24,236.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Apr 2023

OK