

Our Job Ref No : 305550878

Date : 19.04.2023

ComfortDelGro Engineering Pte Ltd 59 Lovang Drive Singapore 508969

		-		59 Loyang Drive Singapore 508969				
FINA	LIZAT	ION FORM						
То	: _		LKK		Fax	i		
Attn	•		RASUL					
Vehic	cle Re	No. : SHC	2045Y					
The	survey	and estimates o	f the repairs of the above-me	ntioned vehicl	e are as follo	ws:-		
Z	The	repair job shall b	INCOME		SCJ8871L			
2.	The	The finalized amount shall be:						
	(a)	Spare Parts af	ter List discount			-		
	(b)	Labour Charge	es					
		Total for Part-	By-Part Repair Cost			12		
	(c.)	Lumnsum Ren	air (if applicable)					
	(0.)	Total for Lump	sum repair cost after Less:					
		Final Lumpsu	m Repair cost			\$2,500.00		
5.	Than	k you for your as	sistance.	We confirm the estimates and finalized amount				
	Signa	iture:(		_ Sig	gnature:	King		
	Name	: CHIANG		_ Na	me : _	RASUL		
	Tel	6214831	14	_ Da	ite : _	20/04/23		
	Fax	6546815	56	_				
For O	fficial	Use Only						
Item			Amount	Document Attached Yes or No	Confirm By (Signature)			
Rental Rate P/Day				YES				
2. Loss of Income Paid			140	N				
3. Survey Fees			-:					
LTA Search Fee     Medical Fees (on behalf			\$26.75/\$2.00	YES				
		if applicable)						
6 Overrun								

Remarks:			
-			