

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23003788/Rwp3m4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	04-05-2023 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLB 9495T	Veh. Ir	spected	SHA 4984J	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1217572-002	Exces	s (\$)	0.00	
	Assign From		Assigr	n Date	10/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40 1.7 CRDI	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU090000	Colou	•	BLUE	
	Odometer	956070	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	GITI		6 mm	
	L/H Front Tyre	205/60 R16	GITI		6 mm	
	R/H Rear Tyre	205/60 R16	GITI		6 mm	
	L/H Rear Tyre	205/60 R16	GITI		6 mm	
4. Description of Damages						
	THE VEHICLE SU	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/04/2023	Inspection Date 10/04/2023			
	Survey held at	at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					