ASS. REC. BY: Steve REF: CS 3/ASM72000900/Ety3	
	Veh No: FBR 71044 Yr Regn: 28/9/20
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD ITP WS ITP RES I OD RES I EVA I INV I MY	Truck / Trailer or
To Inspect Vehicle No:	Make: Hondy ADVISEA c.c 150
at Workshop m/s	Colour Black A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio; Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: KF381007150 .
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modl: NII / STRIM / STD A/RIM or
×~	Tyre Size: F: //0/80 -/4
(Policy Condition)	R: 130/70-13
Remark: The veh had commenced its · N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 11,500	Front Rear Class
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. W mm . R/Bal. W mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. mm L/Bal. mm
Est. Repairs: 3 days Res.: Yes or No	D.O.A. 1711/1/2 Dikas D.O.I. 161/1/2
Lum Sum: 20 % 3 Val.: Yes or No	survey held at Bikers Avenue
CA / REV / REP. / 24 HRS	Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT Date: Person Contacted:	
Data / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
MV - 11,500	
Repair range 2	c - 3k 4 days
SUBMIT PRS RE	<u>-PORT </u>
3/04/2023 Submit L/S \$2,250.00 @ 3 days (Red	\$1,950.00/46%)
Date/Time, File Pass to? 13/04/2023: Prell. Report	Days Of Repair: 3
1) Typist : Final Report F	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Add Fee:	
Down Frances D	: Interview (\$) Photos
Report Format: Paper Survey	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$ L/S \$2,250)	:Weekend (\$)
	TOTAL