

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC23003803/Any3e2	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	25/05/2023	
	ATTN: MARCUS X	IAO		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNE 4273K	Veh. Inspected	d	SLF 5527R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1218014-002	Excess (\$)		0.00	
	Assign From	JESS TOH	Assign Date		12/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	RU11203731	Colour		BLUE	
	Odometer	342631 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Front Tyre	215/60 R16	DUNLOP		6 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP		6 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
					1.0	
5.	General Information					
	Accident Date	10/04/2023	Inspect Date /	Time	13/04/2023 (05:16 PM)	
	Survey held at HD PERFECT AUTOWORK PTE LTD					
		8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					
	1					