

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
Repairer Reference: GBC6626R OD CHINA
Date calculated: 12/04/2023 11:27 AM

Full Report
Registration: GBC6626R
Printed: 12/04/2023 11:28 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:		Date of Incident:	04/04/23
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	NISSAN
Model:	ATLAS F24
Sub Model:	BASE MODEL
Model Sheet Number:	71 94 01
Registration:	GBC6626R
VIN number:	
Odometer:	

Model Specs

FROM 12.2013	AIR CONDITIONING	DOOR MIRROR WITH ARM	3.0 LTR 110KW
SINGLE CAB	PRODUCTION IN JAPAN	TWO COAT METALLIC	PREPARE OFF VEHICLE

Tanjin 17495349/62503561
Not Authorise Ex: \$500
c/s Resurvey after repair
tanjin@khand.com
7 days 13/4/23 01/30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	-------------------------	------------------------	------------------------	-------------------------	-------------------------	--------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
UA10A1)	R + R FRONT BUMPER		6.0	25.20
UA10A1)	RENEW FRONT BUMPER (REMOVED)		2.0	8.40
NO NUMBER	R + R TYPE BADGE		3.0	12.60
RE20A1)	R + R LEFT HEADLAMP (FRONT GRILLE REMOVED) INCLUDES: REQUIRED COVERS REMOVE AND REFIT. ADJUST HEADLAMPS.		5.0	21.00
RE20A1)	R + R RIGHT HEADLAMP (FRONT GRILLE REMOVED) INCLUDES: REQUIRED COVERS REMOVE AND REFIT. NOT INCLUDED: ADJUST HEADLAMPS.		3.0	12.60
NO NUMBER	R + R FRONT SKIRT		2.0	8.40
NO NUMBER	R + R FRONT VENTILATION GRILLE		2.0	8.40
NO NUMBER	R + R BADGE NISSAN		3.0	12.60
NO NUMBER	RENEW FRONT PANEL		90.0	378.00
RG12A1)	R + R WIPER MOTOR		1.0	4.20

Code	Description	WU	Price SGD
UG10A2	R + R WINDSCREEN INCLUDES: INTERIOR MIRROR, BOTH TRIMS A-PILLAR, WIPER ARMS, COWL PANEL, AND REQUIRED ATTACHED PARTS R + R	11.0	46.20
RG24A1)	R + R WIPER LINKAGE	1.0	4.20
NO NUMBER	ADD OUTER MIRROR REMOVE AND REFIT	2.0	8.40
UH40A1	R + R R/F DOOR TRIM	3.0	12.60
VC10A1	R + R INSTRUMENT PANEL CPL INCLUDES: R + R COVERS, GLOVE BOX, INSTRUMENT HOUSING AND STEERING WHEEL	25.0	105.00
TB10A2)	R + R HEATING	4.0	16.80
TB1011	ADDITIONAL FOR AIR CONDITIONING	1.0	4.20
NO NUMBER	DRAIN-REFILL COOLENT LIQUID	3.0	12.60
TB7772	DRAIN/REFILL AIR CONDITIONING	6.0	25.20
1481	LEFT FRONT DOOR REPAIR	20.0*	84.00
1482	RIGHT FRONT DOOR REPAIR	30.0*	126.00
2274	R/INN A-PILLAR REINF REPAIR	30.0*	126.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		25.30	253.0
Total of Labour			1,062.60

Paint

Paint Work		SYSTEM AZT		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD		
	FRONT PANEL NEW PART PAINTING	31.0			
	FRONT AIR GRILLE NEW PART PAINT K1N	5.0			
	R/HEADLAMP TRIM NEW PART PAINT K1N	4.0			
	R/F WIND DEFLECTOR NEW PART PAINT K1N	5.0			
	FRONT AIR VENT TRIM NEW PART PAINT K1N	6.0			
	R/F AIR VENT GRILLE NEW PART PAINT K1N	4.0			
	LEFT FRONT DOOR REPAIR PAINTING >50%	27.0			
	RIGHT FRONT DOOR REPAIR PAINTING >50%	27.0			
	R/INN A-PILLAR REINF SURFACE PAINT	4.0			

Paint Material Per Part

Code	Description	Price SGD
0900	FRONT PANEL NEW PART PAINTING	43.45
0410	FRONT AIR GRILLE NEW PART PAINT K1N	10.12
0422	R/HEADLAMP TRIM NEW PART PAINT K1N	1.12
0888	R/F WIND DEFLECTOR NEW PART PAINT K1N	11.24
1392	FRONT AIR VENT TRIM NEW PART PAINT K1N	17.42
1396	R/F AIR VENT GRILLE NEW PART PAINT K1N	2.81
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	39.50
1482	RIGHT FRONT DOOR REPAIR PAINTING >50%	39.50
2274	R/INN A-PILLAR REINF SURFACE PAINT	1.25

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		113.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	14.60	146.0	613.20

42.00 SGD/h

10 WU/h

Material Cost - Paint

	Price SGD
New Part Painting	43.45
New Part Painting - Plastic K1N	42.71
Repair Painting	79.00
Surface-/Blend Paint	1.25
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	207.71

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD
0257	FRONT NUMBER PLATE	KNPL3	Original	0.00
0281	FRONT BUMPER CPL	62010 MD81A	Original	420.00
0410	GRILLE	62320 MA000	Original	300.00
0422	R/HEADLAMP TRIM	75893 MA00A	Original	60.00
0431	BADGE	99081 MB40C	Original	65.00
0432	BADGE MODEL	65092 LC65B	Original	50.00
0561	LEFT HEADLAMP ASSY	26060 MA00A	Original	260.00
0562	RIGHT HEADLAMP ASSY	26010 MA00A	Original	260.00
0888	R/FRONT PANEL	F1262 MA0AA	Original	240.00
0900	FRONT PANEL	F1200 MD20A	Original	650.00
1391	RUBBER SECTION	63826 MA00A	Original	50.00
1392	FRONT AIR VENT TRIM	61874 MA030	Original	300.00
1396	R/F AIR VENT GRILLE	61876 MA160	Original	70.00
1401	WINDSCREEN	72712 MA00A	Original	450.00
1410	WINDSCREEN BOND KIT	G2891 89925		0.00
1411	FRONT SCREEN FILLING	G2G16 89900		0.00
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS		
1414	SPACER	72714 0P005		0.00
1415	FRT SCREEN SUPPORTS	79714 D4000		0.00
1428	R/UPP W-SCREEN MLDG	72750 MA00D	Original	90.00
1450	WIPER MOTOR	28815 MA000	Original	350.00
1451	L/FR WIPER ARM	28886 MA000	Original	70.00
1452	R/FR WIPER ARM	28881 MA000	Original	70.00
1455	L/F WIPER BLADE	28890 MA000	Original	30.00
1456	R/F WIPER BLADE	28890 MA000	Original	30.00
1461	WIPER LINKAGE CPL	28840 MA000	Original	80.00
1738	R/DOOR MIRROR ASSY	96301 LC63A	Original	150.00
1741	R/DOOR MIRROR	96331 5T002	Original	60.00
4411	HEATER CPL	27110 MA01A	Original	1,250.00
4412	HEATER BLOWER MOTOR	27200 MA00B	Original	500.00
1001	FRT GRILLE CLIP (+)	-	Original	50.00
1002	FRT GRILLE CLIP (-)	-	Original	50.00
1003	FRT WIPER PANEL SIDE	TOP COVER RH	Original	70.00
1004	FRT WIPER ARM SIDE	COVER RH	Original	35.00
1005	FRT WIPER ARM SIDE	COVER LH	Original	35.00

Code	Description	Part Number	Part Source	Price SGD
1006	FRT SIDE MIRROR	RECTANGULAR RH	Original	<i>car</i> 120.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			6,215.00
u: Used parts	Total			6,215.00

Extras

Code	Description	Price SGD
1000	FRT NUMBER PLATE -	<i>bt</i> 25.00*
1007	FRT WINDSCREEN SEALANT	<i>we</i> 40.00*
1008	ERP BRACKET -	<i>we</i> 26.00*
1009	ROC STICKER RH	<i>?</i> 20.00*
1010	ROC STICKER LH	<i>?</i> 20.00*
1011	TO CHECK WIRING -	<i>?</i> 30.00*
1012	TOP UP AIR CON GAS -	<i>?</i> 50.00*
1013	TO DIAGNOSE & RESET FAULT CODE	<i>?</i> 150.00*
	Total Extras	361.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	6,215.00	6,215.00
Labour Time Base 10 WU/h		
Total 253.0 WU X 42.00 SGD/h	1,062.60	
Total of Labour		1,062.60
Total Of Extras		361.00
Paint Work Time Base 10 WU/h		
Labour Cost 146.0 WU X 42.00 SGD/h	613.20	
Material Cost	207.71	
Total Paint Including Material		820.91
Repair Cost Excludes GST		8,459.51
GST (+8.0%)		676.76
Repair Cost Included GST		9,136.27

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	214W
Vehicle Details	
Vehicle No.:	GBC6626R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Apr 2023
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD
Primary Colour:	Gold
Manufacturing Year:	2013
Engine No.:	ZD30324555K
Chassis No.:	JN1SC2F24Z0855107
Maximum Power Output:	-
Open Market Value:	\$30,277.00
Original Registration Date:	27 May 2013
First Registration Date:	27 May 2013
Transfer Count:	0
Actual ARF Paid:	\$1,514.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 May 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$56,011.00
COE Rebate Amount:	\$407.00
Total Rebate Amount:	\$407.00

The information contained herein is correct as at 05 Apr 2023

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	04/04/2023 17:10 (SGT)
Reported by	Actual Driver
Date of Accident	04/04/2023 06:25 (SGT)
Exact Location of Accident	BKE, Singapore
Additional Location Information	TOWARDS KJE (PIE TUAS) EXIT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC6626R
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	SHING LECK ENGINEERING SERVICE PTE. LTD.
Company Reg No	2XXXXX214W
Email Address	JANICE.SHIA@SHINGLECK.COM
Mobile Phone No	(Phone) +65-97366296
Alternative Phone No	(Office) +65-63168490

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Cabstar
Variant	3.0 5M/T ABS 2DR 2WD
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2953

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNW00060912208

DRIVER

Name of Driver	NEO SWEE SAI
NRIC No	SXXXX734Z
Date Of Birth	07/04/1957
Occupation	Outdoor

Date Of Driving Pass	13/07/1979
Driving experience	43 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97954798
Alt. Phone Number	-
Email Address	JANICE.SHIA@SHINGLECK.COM
Address	BLK 33 MARSILING DRIVE #11-369
Address complement	-
Postcode	730033
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 04/04/2023 @ ABOUT 0625 HRS. I WAS TRAVELLING ALONG BKE TOWARDS KJE (PIE, TUAS) EXIT. VEHICLE B INFRONT OF ME SUDDENLY APPLY BRAKE AND STOPPED. I COULDN'T STOPPED IN TIME AND COLLIDED ONTO THE REAR OF VEHICLE B. I DIDN'T MANAGE TAKE DOWN ANY ACCIDENT SCENE PHOTO AS MY HANDPHONE IS SPOILED AND DIDN'T TAKE DOWN ANY PARTICULUR OF THE THIRD PARTY DRIVER.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG1786Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

A- GBC6626R
B- GBG17862
C (Van)

KSE CPE, Tuas

vJun2022

1

Describe Circumstance of the Accident

On 04/04/2023 @ about 0625 hrs. I was travelling along BKE towards KJE (PIE, Tuas) exit. Vehicle B in front of me suddenly apply brake and stopped. I couldn't stop in time and collided onto rear of Vehicle B. I didn't manage take down any accident scene photo as my handphone is spoiled and didn't take down any particular of the third party driver.

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other workshop
☐ For record purpose

Policy No. DMVSNW00060912208
Insurer China Veh. No. GPC6626

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT MY OWN DAMAGE CLAIM UNDER MY POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

g.

Driver's Signature (if driver is not the policyholder) / Date & Time

3

SNG AH TEE MOTOR & PANEL SVC PTE LTD

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)