

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	GREAT AMERICAN	N INSURANCE COMPANY	Ref:	CS/GAI23003808/Kqy3m4	
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	AL TOWER	Date:	03/05/2023	
			Code:	GAI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 9452P	Veh. Inspected	SMV 1206Y	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CLMOMVC000004329	Excess (\$)	0.00	
	Assign From	ELIZABETH CHEW	Assign Date	13/04/2023	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS (A)	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	MR2BE3BE500010990	Colour	METALLIC BLUE	
	Odometer	30220 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	MICHELIN	7 mm	
	L/H Front Tyre	205/55 R16	MICHELIN	7 mm	
	R/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
	L/H Rear Tyre	205/55 R16	MICHELIN	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/04/2023	Inspection Date	13/04/2023	
	Survey held at	CHENG HOE MOTOR PL			
		BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				